

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 5 & 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 73 dated June 8, 1857 - (DCSO Records Vol 16 Pg 6660

Set ¼ sec. post, from which
A chinquapin, 10" dia., bears S.44°E., 100 lks.
A fir, 15" dia., bears S.28°W., 85 lks.

GLO corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 16 Pgs 6700-1)

The ¼ sec. corner is nearly obliterated. The old corner, which was a post, has disappeared & the chinquapin, described as BT in sec. 5 has fallen & decayed. I destroy the old marks and reestablish the corner in its orig. position as follows:
A R.Fir 30" dia., for ¼ sec. corner, I mark ¼ S6 on W and 5 on E side; from which
A W.Fir, 14" dia., bears N.54°E., 36 lks., mkd: ¼ S5 BT.
A W.Fir, 18" dia., bears N.80°W., 24 lks., mkd: ¼ S6 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones - W. Penley - Jan. 1968 - C.S. File 54/59-26

Found - 30" R.Fir corner tree, now 34" stump, found scribe on W face.
18" W.Fir now 20" stump, N.80°W., 15.8 ft. opened & fd. scribe.
Set brass cap on N side of corner tree at ¼ cor. mkd:
COUNTY SURVEYORS T30S R1W
OFFICE 1968 ¼ S6|S5
New BTs- 11" W.Fir S.89°E., 46.1 ft. mkd: ¼ S5 CS BT.
8" W.Fir S.61°E., 32.6 ft. mkd: ¼ S5 CS BT.
Note - There are no trees in west within scribing distance.
Fence is 5.0 ft. north of the ¼ corner running E & W.

Glen Baughman - For: US Forest Service - April 1979 - C.S. File 58/176-027A & 027B

Found - 1" iron pipe with 1968 County brass cap.
11" now 14" W.Fir S.89°E., 46.1 ft.
8" now 10" W.Fir S.61°E., 32.6 ft.
Set - I marked a 6" D.Fir S.32°W., 21.9 ft. "¼ S6 BT" and attached a brass washer stamped Land Surveyor 536 on lower face.

continued next page

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 5 & 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Stephen J. Flause, Deputy -
Terrie Plouff - Karen Mosley - Feb. 26, 1981 - C.s. 61/19-9

Found - From 1905 resurvey, a red fir, 30" diam. marked as
the corner tree is now a 34" diam. approx 4 foot
tall rotted fir stump, an open and burned blaze
on its west face has the scribing 4 S6 visible,
the east face is burned and has a blaze but no
scribing is visible.

A 1968 County Brass cap, 2½" on a 1" I.P. protrudes
15" above ground & bears North 2.0 ft. from above
corner. Cap marked "County Surveyor T30S R1W ¼ 6
5 1968".

No accessories from orig. 1857 survey are found. These were
destroyed in 1905 resurvey.

Found - From 1905 survey, A W.Fir, 18" now an 18' dia.
rotted fir stump bears N.80°W., 15.8 ft. from
1905 corner tree. Has a single blaze with
scribing ¼ S6 BT visible.

No evidence of other 1905 BT is found.

From 1968 Ren. two trees are found; bearings and distances
are checked from the brass cap monument:

An 11" W.Fir now a 15" DBH W.Fir bears S.84°E., 45.4
ft. (Rec. S.89°E., 46.1 ft.) Tree has partially
healed double blaze with the scribing S5 CS
visible.

An 8" W.Fir now a 12" DBH W.F bears S.56°E., 32.6
ft. (Rec. S.61°E., 32.6 ft.) Thee has partially
healed double blaze with some illegible scribing
visible.

Note - Variation of bearing and distance from record in the
preceding two bearing trees probably resulted
from an improperly declinated compass and an
improperly reduced slope distance.

A 6" D.Fir now a 6" DBH D.Fir bears S.32°W., 22.4
ft. (Rec. S.32°W., 21.9 ft.) Tree has double
blaze with scribing 1/4 S6 BT visible. 1979

Monument location is accepted. The following markings are
added to the brass cap monument "W ↴" The arrow points south
to the corner tree.

All accessories are tagged with new DCSO bearing tree tags.

FD. BC with BTs, H. Pieske - 9/1993 - M117-62

continued next page

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 5 & 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby, LS 1654 - Ryan Palmer - J. Leonard - 11/25/2009 -
C.S. File 65/66-54

Found - Orig. corner stump with spike.
DCSO brass cap (properly marked)
12" Fir S.32°W., 22.4 ft.
11" Cedar N.42°W., 10.1 ft. (RFP 10/93 tag)
21" Fir S.63°E., 30.8 ft.
20" Fir S.89°E., 44.9 ft.