

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7472

Set 1/4 sec. post, from which
A fir, 12" dia., bears S.75°W., 40 lks.
A fir, 12" dia., bears N.85°W., 70 lks.

Douglas Co. Surveyors Office - John M. Powell - 8/1968 - C.S. File 54/71-101

Reported as not found.
Found old location tag 280 East of cor. Now this cor. apparently lies in shale pit.

J.A. Hoffbuhr - For: Umpqua Nat'l Forest - 8/28/1972 - M42-70

Set - 2"x30" galv. Iron pipe with 3" Brass Cap WC Stamped:
T 31 S R 1 W Witness Corner

¼ Cor. $\frac{S\ 29}{S\ 32}$

South 20 ft. to True cor.
Ore. Lic. 222
1972

from which:

12" W.Fir bears S.24¾°W., 180.5 ft. scribed W.C. ¼ S32
T31S R1W RS222 BT.

10" D.Fir bears N.36½°E. 81.4 ft. scribed W.C. ¼ S29
T31S R1W RS 222 BT.

John Ransom, USFS - Jonathan Drew - 1/8/2014 - C.S. 65/85-3

Condition report

Found - 3" brass cap (properly mkd) on 2½" iron pipe, projecting 5" above a large mound of stone. Cap and pipe are slanted heavily North, no clear sign of what may have caused this.

20" D.Fir (N.35°56'E.) (82.1 ft) healed single blaze (13") W.Fir (S.24°21'W.) (179.3 ft) tree not visited, can be seen from corner and lies on top of quarry cut, tree is healthy.

() = Record per M81-58

No new accessories added.

New nails in BT tags & painted faces & 6" band at head height
Brush cleared around monument and to BTs "LAND LINE" flagging tied on monument and guard posts.

Property line maintained east 600 ft +1- to Elk Creek this date.

continued next page

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Note - Witness corner falls on top of quarry cut, true corner falls in quarry, posted line ends about 120 ft east of true corner. From 4x4 post at highway, go west on posted/blazed line to property post at top of quarry, follow quarry top westerly to find witness corner.

Jonathan B. Drew, II, USFS - Assisted by: Andrew Hillman,
Survey Tech - 7/14/2015 - M169-67 & C.S. File 65/90-59 & 60

Witness corner

Found - A 3" brass cap on 2½" galvanized iron pipe, leaning heavy to the north and projecting 5" above a mound of stone. Unpack stone mound, straighten pipe & re-pack stone, monument now projects 1" above a mound of stone.

A 19" Fir bears, S.24°24'W., 179.4 ft, with a healed double blaze (S.24°21'W., 179.3') 1979

A 20" Fir bears, N.35°37'E., 81.7 ft, with a healed double blaze. (N.35°56'E., 82.1') 1979

Clear brush from around monument and to BTs. Tie flagging to monument & guard posts, paint BT faces & a 6" band at head height. Add new nails to existing BT tags & add new tags where needed.

Tie: center ¼ section 29 bears N.0°9'28"E., 2648.84 ft, (N.0°9'59"E., 2648.60 ft) 1972

Tie: true ¼ sections 29 & 32 BEARS. S0°9'28"W., 20.00 ft, (S.0°9'59"W., 20.00 ft) 1972

LATITUDE: N.42°50'36.19323" LONGITUDE: W.122°51'12.76829"

ELLIPSOID HEIGHT: 1706.1 FT

DATUM: NAD_83(2011) (EPOCH:2010.0000), GEOID 2009

SOURCE: Direct occupation gps & traverse tie, opus corrected base.

QUARTER CORNER

Found - No monument at corner position, found witness corner per M42-70.

Set - A 5/8"x30" rebar with a 2" aluminum cap projecting 2" above a mound of stone.

New - (Use BTs for WC by Hoffbuhr per M42-70)

A 19" Fir bears, S.27°18'W., 161.4 ft, with a healed double blaze.

A 20" fir bears, N.28°51'E., 98.7 ft, with a healed double blaze.

Note - Corner falls at the toe of a cut bank for an old quarry road.

LATITUDE: N.42°50'35.99583" LONGITUDE: W.122°51'12.76915"

ELLIPSOID HEIGHT: 1691.4 FT

DATUM: NAD_83(2011) (EPOCH:2010.0000) SOURCE: TRAVERSE TIE FROM GPS CONTROL, OPUS CORRECTED BASE.