

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 18 Page(s) 7473</p> <p>-----</p> <p>Set ¼ sec. post and built stone mound, from which An Oak, 12" dia., bears S.73°W., 18 lks. An Oak, 12" dia., bears N.52°W., 22 lks.</p>
<p>Douglas Co. Surveyors Office - John M. Powell - 8/1968 - C.S. File 54/71</p> <p>-----</p> <p>Reported as not found. Found - Old mound of stone with possible BTs, either cut for fence posts on burnt with young(?) oaks coming from stumps; Also good dist. from creek, however not enough evidence to renew.</p>
<p>J. A. Hoffbuhr - For: Umpqua Nat'l Forest - Aug. 8, 1972 - M42-70</p> <p>-----</p> <p>Found Stone Mound. Set 2"x18" galv. IP with 3" Brass Cap in concrete &amp; stamped: T31S R1W ¼ <math>\frac{S\ 20}{S\ 29}</math> Ore. Lic. 222 1972</p> <p>Found stump hole with Oak sucker shoots N.52°W. 14.5 ft. Found stump hole with Oak sucker shoots S.73°W. 11.9 ft. 16" P.Pine BT bears N.17¼°W. 40.0 ft. scribed ¼ S20 RS222 BT 12" D.Fir BT bears S.6½°E. 24.8 ft. scribed ¼ S29 RS222 BT</p>
<p>John Ransom, USFS - Jonathan Drew - 1/15/2014 - C.S. 65/85-4</p> <p>-----</p> <p>Found - 3" brass cap on 2½" iron pipe, flush in a mound of stone. 20" P.Pine (N.17°15'W.) (40.0 ft) healed double blaze 5" Oak (N.52°W.) (14.5 ft) healed double blaze 19" D.Fir (S.6°30'E.) (24.8 ft) Record is oak shoots, at record distance is burl of a young oak. ( ) = RECORD PER M42-70</p> <p>Corner falls on nearly level ground, about 300 ft NE from a switch back on FS RD 1610-300. E-W fenceline about 10 ft North Brush cleared around monument and to BTs "LAND LINE" flagging tied on monument and guard posts</p> <p><b>No new accessories added</b></p> <p>New nails in BT tags and painted faces &amp; 6" band at head height Property line maintained East .25 and West .25 miles</p>