

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34 only (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7461)

-----  
Set post cor. secs. 33, 34, 3 and 4, from which  
An Alder 36" dia., bears S.50°W., 50 lks. dist.  
A Maple 12" dia., bears N.25°W., 30 lks. dist.  
A Fir 15" dia., bears N.45°E., 45 lks. dist.  
A Fir 24" dia., bears S.40°E., 45 lks. dist.

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7487-88)

-----  
The old sec. cor. to secs. 33 and 34, which is a decayed post with 3 BTs still standing. I destroyed this post and replaced it with a basalt stone, 18x9x7 ins., 12" in the ground for cor. to sec. 33 and 34 mkd. with 3 notches on E. and W. edges, from which  
A Fir 28" dia., bears N.45°E., 45 lks. dist. mkd. T31S R1W S34 BT.  
A Maple 12" dia., bears N.25°W., 30 lks. dist. mkd. T31S R1W S33 BT.  
A Fir 40" dia., bears S.40°E., 45 lks. dist. mkd. T32S R1W S4 BT.  
An Alder described in field notes or original survey has fallen. The three bearing trees were newly marked.

Arthur Boyer, Surveyor - Wit: Ted Schattenkerk - Sept. 1949 -C.S. File 40/214

-----  
Found rock in place for this sec. corner; all four recorded trees are alive and all are as given in the recorded field notes except, the 40" Fir tree which is recorded as being S.40°E., 45 lks., which measures from the corner rock 36 lks. This tree is mkd. or scribed distinctly "S3". It is in sec. 4 not 3. This corner is of course for secs. 33 & 34 only and not for either 3 or 4.

Douglas Co. Surveyors Office - John M. Powell, and crew - July 25, 1968 - C.S. File 54/71-26

-----  
Found - No trace of corner stone.  
28" now 32" D.Fir, almost dead, N.45°E., ~~39.7~~ 29.7 ft. shows good scar.  
40" D.Fir, now burnt stob, S.40°E., faint burnt scribe visible.

(Cont. Next Page)

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34 only (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

12" Maple, now dead, N.25°W., 19.8 ft., rotten face,  
old axe work and faint marks.

This corner now lies on East edge of Elk Creek in dangerous  
place, therefore, SET WITNESS Corner 50.0 ft. East of Tree  
corner, mkd: County Surveyors Office 1968

W.C. 50.0' West to T31S R1W

S33 | S34

S 4

T32S

New BTs- 10" Ash S.6½°W., 11.4 ft. mkd. W.C. T32S R1W S4 CS  
BT.

9" Ash N.66°W., 16.8 ft. mkd. W.C. T31S R1W S34 CS  
BT.

This cor. lies on top of creek bank 2.50 ft. South of fence  
line.

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff  
Lorsung - 6/3/2019 (filed 1/28/2021) - C.S. File 67/48-20

Found - A 1" I.D. iron pipe by Powell, in 1968, firmly set,  
projecting 15" above the ground with a 2½" dia.  
brass cap (properly) marked

BTs by Powell in 1968 -

A 12" dia. Ash bears S.6½°W, 11.4 ft with scribe  
marks visible on a partially healed blaze.

A 15" dia. Ash bears N.66°W., 16.8 ft with a  
healed blaze.

All other accessories were washed away by the stream

New BT - A 34" dia. W.Oak bears North, 170.8 ft, scribed "WC  
T31S R1W S33" & "CS BT" on a double blaze.

Note - Compass declination 14¼°E.

The Witness Corner falls on the high bank of Elk  
Creek in open pasture land approximately 250 ft  
South Westerly of the ranch house and 300 ft  
South of the ranch road.

All BTs have BT Tags attached. All new BTs have  
double blazed faces with bearing measured to the  
center of the tree at the root crown and  
distances measured to a 4" Mag Hub in the side  
and center of the root crown.

Geodetic coordinates

Latitude: 42°49'43.29"N.

Longitude: 122°49'24.62"W.

DATUM: NAD 83

SOURCE: GeoXT6000