

TOWNSHIP 31 RANGE 01 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7573-4)

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked

1/4 $\frac{S \ 2}{S \ 11}$
1923

from which

- A cedar, 18" dia., bears N.83°E., 17 lks., mkd: 1/4 S2 BT.
- A fir, 30" dia., bears S.80°E., 27 lks., mkd: 1/4 S11 BT.

Douglas Co. Surveyors Office - John M. Powell - 10/2/1968 - C.S. File 54/71-67

Reported as not found.

Cor. falls in bottom of drain which is logged and badly burnt. Good line, good call at 40.04 (cor. at 40) Bottom of draw full of down and burnt logs.