

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 1 only, T31-3

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

<p>GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7703) ----- A Laurel 4" dia., which I mark ¼ S on W. face, for ¼ sec. cor., from which A Fir 26" dia., bears S.45°W., 27 lks. mkd. ¼ S BT. A Laurel 13" dia., bears S.88°E., 35½ lks. mkd. ¼ S BT.</p>
<p>GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page 7618) ----- The Qr. sec. cor. nearly obliterated. The Cor. tree is dead and decaying. I reestablish the cor. in its original position for sec. 1, T31S R3W., only, as follows: No stones obtainable. Set Madrone post 3 ft. long, 4" sq., 24" in the ground for qr. sec. cor. on W. bdy. sec. 1, marked qr. on W. face, from which A Madrone 8" dia., bears N.41½°W., 41 lks. mkd. ¼ S1 BT. A Fir 30" dia., bears S.50°W., 27 lks. mkd. ¼ S1 BT.</p>
<p>Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - March 1970 - C.S. File 54/28-99 ----- Found - Unrecorded 1" I.Pipe, N.48°W., 2.8 ft. 30" D.Fir now snag, S.50°W., 17.8 ft., tree opened, burnt face. 8" now 12" Laurel N.41½°W., 27.1 ft., opened for scribe "S" and other marks, rotted face. Set Brass cap at cor. mkd: County Surveyors Office R T 31 S R 3 ¼ 2 W S 1 W 1970 New BTs- 12" D.Fir N.12°W., 52.0 ft. mkd. ¼ S1 CS BT. 16" Laurel N.87°W., 17.0 ft. mkd. ¼ S1 CS BT.</p>
<p>Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27 ----- Found - Brass cap per 1970 DCSO renewal 38" D.Fir snag S.50°W., 17.8' no visible scar 13" Laurel N.41°W., 27.1' healed face 18" D.Fir N.12°W., 52.0' healed face 19" Laurel N.87°W. 17.0' open scar, scribe un-readable.</p>