

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7653-54)

No stones obtainable.
Set a Fir post 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 17, 18, 19 and 20 marked T31S S17 on NE.; R2W S20 on SE.; S19 on SW.; S18 on NW. face, with 3 notches on S. and 5 notches on E. edge, from which
A Fir 30" dia., bears N.50°E., 189 lks. dist. mkd. T31S R2W S17 BT.
A Hemlock 6" dia., bears S.48°E., 64 lks. dist. mkd. T31S R2W S20 BT.
A Fir 6" dia., bears S.20°W., 68 lks. dist. mkd. T31S R2W S19 BT.
A Fir 30" dia., bears N.28½°W., 56 lks. dist. mkd. T31S R2W S18 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Aug. 1966 - C.S. File 54/28-65

Found - 30" Fir, now down, N.50°E., 124.7 ft.
30" Fir, now snag, N.28½°W., 37.0 ft., opened for scribing "R2".
6" Fir S.20°W., 44.9 ft., shows good scar.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 2 W
S 18 | S 17
S 19 | S 20
1966
New BTs- 12" Cedar N.5°E., 28.6 ft. mkd. T31S R2W S17 CS BT
21" D.Fir N.62°E., 19.6 ft. mkd. T31S R2W S17 CSBT
12" D.Fir S.33°E., 12.5 ft. mkd. T31S R2W S20 CSBT
No good trees in NW. quad.