

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION East 1/4 cor. for Sec. 20 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7648)

No stones obtainable.

Set a Yew post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. on E. bdy. sec. 20, marked ¼ S20 on W. face, from which

A Fir 30" dia., bears N.27°W., 25 lks. dist. mkd. ¼ S20 BT
A Hemlock 8" dia., bears S.50°W., 22 lks. dist. mkd. ¼ S20 BT.

Douglas Co. Surveyors Office - L.E. Monrean; P. Earle; J. Cook; Dec. 15, 1975 - C.S. File 57/39-33

Found - A rotted Hemlock 12" dia. broken off approx. 1 ft. above ground, stump firmly in place, bears S.50°W., 14.5 ft. Downed tree is scribed "¼ S20 BT".

Rotted, burned remains of a Fir, dia. indeterminate, bears N.27°W., 16.5 ft.

Set brass cap at East ¼ corner stamped: Douglas Co. Surveyors Office

T 31 S R 2 W

1/4 S20

1975

New Accessories:

Set spike in 36" dia. Fir stump, bears N.27°W., 40.3 ft. Spike stamped "BO 1".

Set spike in 42" dia. stump, bears N.73°W., 57.9 ft. Spike stamped "BO 2".

The West ¼ cor. of Sec. 21 bears N.2°W., 163.9 ft. (Rec. N.0°03'W., 144.9 ft.)