

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 300503

PRIMARY CORNER DESCRIPTION Cor for Secs 9 and 16 only (West)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7606)

Set post cor. secs. 8, 9, 16 and 17, from which
A Laurel 10" dia., bears S.88°E., 13 lks.
A Laurel 6" dia., bears N.50°E., 36 lks.
A Pine 24" dia., bears S.1°W., 125 lks.
A Fir 48" dia., bears N.34°W., 63 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7659-60)

The old cor. of secs. 8, 9, 16 and 17 is nearly obliterated. The only remaining evidence being the SW. bearing tree. I reestablish the cor. in its original position as the cor. of secs. 9 and 16 only, as follows:
No stone obtainable.
Set a Madrone post 3 ft. long, 4" sq., 24" in the ground marked T31S S9 on NE.; R2W S16 on SE. face, with 4 notches on S. and 4 notches on E. face, from which
A Madrone 16" dia., bears N.45°E., 39 lks. dist. mkd. T31S R2W S9 BT.
A Madrone 24" dia., bears S.83°E., 14 lks. dist. mkd. T31S R2W S16 BT.
Destroy marks on former bearing tree referring to sec. 17.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - June 1961 - C.S. File 52/81-7

Found both BTs recorded by Mensch. Each shows old scars, centers rotted, no scribing found. Each checks record brg., dist. and size.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 2 W
S 8 | S 9
 | S 16
 1961
New BTs- 6" R.Fir bears S.31°E., 12.0 ft. scribed S16 CS BT
 6" R.Fir bears N.34°E., 31.9 ft. scribed S9 CS BT.