

PRIMARY CORNER DESCRIPTION Cor for Secs 4 and 9 only (West)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7607)

-----  
Set post cor. secs. 4, 5, 8 and 9, from which  
An Oak 24" dia., bears S.10°W., 83 lks.  
An Oak 24" dia., bears N.48°E., 88 lks.  
An Oak 18" dia., bears N.62°W., 88 lks.  
A Pine 36" dia., bears S.73°E., 218 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7679-80)

-----  
The the Sec. cor., which is nearly obliterated. No trace is found of the post. The bearing trees are all standing but deeply overgrown. I reestablish the cor. in its original position as the cor. of secs. 4 and 9 only, as follows:  
Set a basalt stone 18x8x4 ins., 12" in the ground for cor. of secs. 4 and 9 marked with one notch on N. and 5 notches on S. edge, from which  
A B.Oak 30" dia., bears N.47°E., 92 lks. dist. mkd. T31S R2W S4 BT.  
A Y.Pine 40" dia., bears S.72°E., 221 lks. dist. mkd. T31S R2W S9 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - June 1961 - C.S. File 52/81-5

-----  
Foun both BTs, now stumps, as recorded by Mensch. We also find notched corner stone under N-S fence.  
Set Brass cap at cor. and alongside corner stone mkd:  
County Surveyors Office  
T 31 S R 2 W  
S 5 | S 4  
      | S 9  
      1961  
New BTs- 6" Cedar bears S.23°E., 16.5 ft. scribed S9 CS BT.  
8" R.Fir bears N.25°E., 10.5 ft. scribed S4 T31S R2W CS BT.

Survey by William Ruppert - For: U.S. Forest Service - Jan/March 1979 - M 70-57

-----  
Found - 1961 DCSO brass cap and 1" Pipe.  
36" Oak bears S.8½°W., 56.0 ft., good scar.  
34" B.Oak N.60 3/4°W., 57.8 ft., good scar.  
10" Cedar S.23½°E., 16.3 ft., open.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 4 and 9 only (West)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

42" stump S.72½°E., 142.6 ft., burned.  
10" D.Fir N.26¼°E., 10.9 ft., good scar.  
New BT - 9" D.Fir S.8°E., 77.5 ft. scribed T31S R2W S9 BT.

BLM dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group No. 2071, surveyed April/May 2004 - (DCSO records Vol. 55 Page(s) 21383-4)

-----  
The cor. of secs. 4 & 9 only, perpetuated by Byron, in 1961, further perpetuated by Ruppert, in 1979, monumented with the stone set by Mensch, showing 8x4x6" above the ground, with 1 notch on the N & 5 notches on the S faces, alongside & plumbed over which is an iron pipe, 1½" dia firmly set, projecting 18" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

An oak snag, 34" dia., bears S.10°W., 54.8ft., with a healed blaze.

An oak snag, 26" dia., bears N.62°W., 58.1 ft., with a healed blaze.

and the remains of the original BTs reported by Mensch

An oak stump, 30" dia., bears N.47°E., 60.7 ft., with no marks visible.

A pine stump, size indeterminate, bears S.72¾°E., 142.5 ft., with scribe marks BT visible. (Record, S.72°E., 145.9 ft.)

and bearing trees mkd. by Byron

A pine stump, size indeterminate, bears S.72¾°E., 142.5 ft., with scribe marks BT visible. (Record, S.72°E., 145.9 ft.)

and bearing trees mkd. by Byron

A fir, 16" dia., bears N. 23¾° E., 11.2 ft., with a healed double blaze.

A cedar, 15" dia., bears S.22½°E., 15.9 ft., with a healed double blaze.

and the remains of a bearing tree mkd. by Ruppert

A fir snag, 11" dia., bears S.8°E., 77.4 ft., with a healed double blaze.

Corner is located beneath a 4 strand barbed wire fence, extends N.8°W. and S.8°E.

DCSO-GIS Corner visitation - 7/7/2004 - Typed: 2/9/2011 - C.S. File 67/33-1

-----  
Monument - 1.25" BC/IP  
Comment - (needs) rehab