

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 only, T30-2

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6752)

-----

Set post, from which

- A Fir 6" dia., bears S.45°E., 32 lks.
- A Fir 24" dia., bears N.3°E., 50 lks.
- A Fir 30" dia., bears N.3°W., 38 lks.
- A Fir 36" dia., bears S.35°W., 12 lks.

GLO resurvey by Fred Mensch, U.S. Deputy Surveyor - under Contract #766 dated May 10, 1906 (DCSO records Vol. 18 Page(s) 7662-63)

-----

The old cor. of secs. 4, 5, 32 and 33 is nearly obliterated. No trace of the post is found. Two bearing trees are standing with marks deface. I re-establish this cor. in its original position as the cor. of secs. 32 and 33 T30S R2W only as follows. No stones obtainable. Set a Fir post 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 32 and 33 marked T30S S33 on NE. and R2W S32 on NW face, with 4 notches on E. and 2 notches on W. edge, from which

- A Fir 10" dia., bears N.50°E., 58 lks. dist. mkd. T30S R2W S33 BT.
- A Fir 36" dia., bears N.3°W., 40 lks. dist. mkd. T30S R2W S32 BT.

Destroy marks on bearing trees referring to secs. 4 & 5.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Aug. 25, 1966 - C.S. File 54/28-66

-----

Found - 10" now 18" D.Fir N.50°E., 38.2 ft., shows good scar  
36" D.Fir, now down, N.3°W., 26.4 ft., scribe marks visible, but not legible.

Set Brass cap at cor. mkd: County Surveyors Office 1966

T	30	S	R	
S	32	S	33	2
S	4	W		
T	31	S		

New BT - 22" D.Fir N.26°W., 33.5 ft. mkd. T30S R2W S32 CS BT.

Survey by Howard Johnstone - For: Roseburg Lumber Co. - July 15, 1976 - M 56-49

-----

Found - 22" Fir S.26°E., 33.5 ft.  
18" Fir N.50°E., 38.2 ft., down orig. BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 only, T30-2

Alias	Description
Alias	Description
Alias	Description
Alias	Description

36" Fir N.3°W., 26.4 ft., down orig. BT.  
 Reset corner S.26°E., 33.5 ft. from 22" Fir.  
 New BT - 7" Fir N.88°E., 71.9 ft.

Survey by William Ruppert - For: U.S. Forest Service - April 1979 - M 70-61

-----  
 Found - 5/8" Iron rod at uproot of large Fir. No cap.  
 22" D.Fir, good scar, N.25°57'W., 33.9 ft.  
 8" D.Fir scribing partly visible, N.85°44'E., 71.8 ft.  
 SET WITNESS CORNER, a 2" x 30" galv. Iron pipe with 2½" brass cap mkd. "T30S R2W W.C. S32 S33 T31S 85.00 PLS 866 1979".  
 BTs - 15" D.Fir N.57°08'W., 12.5 ft. "W.C. T30S R2W S32 BT"  
 6" D.Fir S.10°21'E., 8.7 ft. "W.C. T30S R2W S33 BT"

Fd Ok by Ken Hoffine 7/1999 M 133-1

BLM dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group No. 2071, surveyed April/May 2004 - (DCSO records Vol. 55 Page(s) 21377-8)

-----  
 The cor. of secs. 32 & 33 only, T 30 S R 2 W perpetuated by Powell, in 1966, from orig evidence no longer in existence, further perpetuated by Johnstone, further perpetuated by Ruppert, in 1979, monumented with an iron rod, 5/8" dia., firmly set, projecting 5" above the ground, with no cap, from which the remains of a bearing tree mkd. by Powell  
 A sawed fir stump, 26" dia., bears N.26¼°W., 33.8 ft., with a healed double blaze.  
 and a bearing tree mkd. by Johnstone  
 A fir, 14" dia., bears N.85¼°E., 71.9 ft., with a healed double blaze.  
 and a reference monument established by Ruppert  
 A galvanized steel post, 2½" dia. firmly set in a collar of stone, projecting 2" above the ground, bears N.0°07'30"E., 83.08 ft. with brass cap mkd. T30S WC S32 S33 R2W T31S PLS 866 85.00 1979 and an arrow pointing to the corner.  
 At the corner point  
 Set a stainless steel post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd.

T 30 S R 2 W  
S 32 | S 33  
 2004

continued next page

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 301700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 only, T30-2

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Deposit the iron rod inside and a magnet in a white plastic case at the base of the stainless steel post.  
Each new bearing tree has a 2½" x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description