

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7634)

-----

No stone obtainable.

Set a Fir post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S28 on N. and 33 on S. face, from which  
 A B.Oak 18" dia., bears N.15°E., 29 lks. dist. mkd. ¼ S28 BT.  
 A Madrone 12" dia., bears S.83°E., 20 lks. dist. mkd. ¼ S33 BT.

Douglas Co. Surveyors Office - L.E. Monrean; P.L. Earle; J.H. Cook, crew - Dec. 17, 1975 - C.S. File 57/39-39

-----

Found - Not of record, a bronze cap 2½" dia. on a 1½" dia. pipe, cap is stamped:

T31S	R2W
1/4	28
	33
30	10

An Oak stump 18" dia., bears N.15°E., 20.0 ft. to center (Rec. 19.1 ft.). Stump is burned and rotted, has a scar, no scribing found.

D.Fir, not of record, 25" dia., bears S.13°E., 12.1 ft. Tree is blazed, I opened blaze and found scribed "¼ S33", scribe on lower blaze not legible.

Did not renew cor. as I could not find scribing in Oak stump.

Survey by William Ruppert - For: U.S. Forest Service - Jan. 1977 - C.S. File 58/137 and M 65-2

-----

Found - Brass cap on 1" galv. I.P., not of record. Bearing and dist. to true corner is S.44°43'E., 11.2 ft.

An Oak stump found with DCSO's tag, no scribing, bears S.14°20'W., 19.5 ft. Stump is burnt and rotted, no scar is discernible. Not of record.

24" D.Fir found tagged and recently cut open, shows scribing "¼ S33" and bears N.15°02'W., 11.9 ft. to brass cap. No record.

Set 2" x 30" galv. I.P. with brass cap mkd. "T31S R2W ¼ S28 S33 RLS 866 1977", 24" of pipe buried. Cairn to cap.

New Accessories:

Steel fence post 4.0 ft. North with signs 54-2 and 54-4 facing West.

14" Cedar bears S.42°41'E., 21.9 ft. scribed "T31S R2W ¼ S33 BT" with "LS 866" disk attached.