

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21 & 22 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7601)

Set post cor. secs. 21, 22, 27 and 28, from which
A Cedar 24" dia., bears S.2°E., 230 lks.
A Cedar 24" dia., bears S.5°W., 51 lks.
A Pine 36" dia., bears N.53°E., 94 lks.
A Pine 30" dia., bears N.67°W., 80 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7643-44)

The cor. of secs. 21, 22, 27 and 28 is nearly obliterated. The cor. which was a stone is not found. The bearing trees are standing with marks overgrown. I reestablish this cor. in its original position for secs. 21 and 22 only, as follows:

Set a serpentine stoen 14x12x10 ins., 9½" in the ground for cor. of secs. 21 and 22 marked with 3 notches on E. edge, from which

- A Pine 10" dia., bears N.20°E., 63 lks. dist. mkd. T31S R2W S22 BT.
- A Pine 36" dia., bears N.67°W., 82 lks. dist., mkd. T31S R2W S21 BT.

Marks on bearing trees referring to secs. 27 and 28 already destroyed.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Aug. 1966 - C.S. File 54/28-72

Found - No sign of corner stone.
10" now 14" Pine, N.20°E., 41.6 ft., scribe visible "T31S R2W S22 BT".
36" Pine, now snag, N.67°W., 54.1 ft. Tree opened, scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 2 W
S 21 | S 22
S 28
1966

New BT - 13" Cedar N.7½°W., 28.8 ft. mkd. T31S R2W S21 CS BT
Sec. Cor. to Secs. 27 & 28 bears East, 110.0 ft.
Also, Cedar S.2°E. about 130.0 ft. scribed "¼ S27".