

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7603)

Set post cor. secs. 9, 10, 15 and 16, from which
A Pine 30" dia., bears S.73½°E., 710 lks.
A Pine 12" dia., bears N.89½°E., 974 lks.
A Pine 30" dia., bears N.2½°W., 1438 lks.
Built stone mound.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7680-81)

The Sec. cor. which is nearly obliterated. The post has been destroyed by decay and the bearing trees are deeply overgrown, are a great distance from the cor. A younger growth of trees makes nearer bearing trees available. I re-establish the cor. in its original position as follows:
A serpentine boulder 3 x 2 x 1½ ft., I mark with a cross (X) at exact cor. point with 4 notches on S. and 3 notches E. of cross, from which
A Pine 6" dia., bears N.72½°E., 277 lks. dist. mkd. T31S R2W S10 BT.
A Cedar 10" dia., bears S.23¼°E., 393 lks. dist. mkd. T31S R2W S15 BT.
No nearer tree available in sec. 15.
A Cedar 12" dia., bears S.32½°W., 247 lks. dist. mkd. T31S R2W S16 BT.
A Cedar 8" dia., bears N.16°W., 120 lks. dist. mkd. T31S R2W S9 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Aug. 1966 - C.S. File 54/28-53

Found - 30" Pine, now down, N.2½°W., 949.1 ft., scribe visible. (Found dist. to be 960.0 ft.)
30" Pine, now stump, S.73½°E., 468.6 ft., stump and part old face, lower face rotten.
No trace of NE. Pine.

Set Brass cap at cor. mkd: County Surveyors Office 1966
T 31 S R 2 W
S 9 | S 10
S 16 | S 15

New BTs- 23" Pine N.½°W., 98.3 ft. mkd. T31S R2W S9 CS BT
24" Pine N.65½°W., 64.2 ft. mkd. T31S R2W S9 CS BT
10" Cedar S.6°E., 29.5 ft. mkd. S15 CS BT.
12" Cedar S.61°W., 101.5 ft. mkd. T31S R2W S16 CSBT

Alias	Description

Douglas Co. Surveyors Office - Gary L. Langlitz; Karen Reed, crew - April 10, 1979 - C.S. File 60/24-22

CORNER REPORT ONLY

- Found - A 1"x36" I.P. with 1966 DCSO brass cap, properly marked, protruding 1 ft. above a 2½" x 2 ft. x 2 ft. x 1 ft. mound of stone.
- A 3 ft. x 2 ft. x 1½ ft. serpentine stone not found.
- A 30" Pine bears N.2½°W., 960.0 ft. (Rec. 949.1 ft.) partial scribing "9" visible. This BT is down and rotted. (Orig.)
- An Orig. 30" Pine, now a 36" stump, bears S.73½°E., 468.6 ft., partial scribing "BT 1" found in this rotted stump.
- I do not find the NE. original BT.
- A 6" Ponderosa Pine, now 26", bears N.74½°E., 178.5 ft. (Rec. N.72½°E., 182.8 ft.) with healed over single blaze.
- A 10" Cedar now a 28" fork of a 3 fork tree, bears S.11°E., 252.6 ft. (Rec. S.23¼°E., 259.4 ft.) with well healed single blaze.
- A 12" I.Cedar now 28" bears S.40°W., 164.1 ft. (Rec. S.32½°W., 163.0 ft) with healed single blaze.
- An 8" Cedar now a 24" fork, of 3 fork tree, 48" dia. at ground level, bears N.21°W., 87.5 ft. (Rec. N.16°W., 79.2 ft.) with healed single blaze.
- A 23" P.Pine now 24", bears N.4°E., 98.3 ft. (Rec. N.½°W.) with visible scribing "T31S R2W S9" in double blaze.
- A 24" P.Pine now 26", bears N.61½°W., 64.2 ft. (Rec. N.65½°W.) with visible scribing "T31S R2W S9 CS" "BT" in double blaze.
- A 10" Cedar now a 10" fork, of 2 fork tree 18" at base, bears S.2°E., 27.9 ft. (Rec. S.6°E., 29.5 ft.) with visible scribing "S15 CS" "BT" in double blaze.
- A 12" Cedar bears S.64°W., 101.5 ft. (Rec. S.61°W.) with visible scribing "T31S R2W S16" "BT" in double blaze.

We left brass cap in position. The 1908 retracement does not state conclusive evidence that the retracement corner was set at orig. position. No bearings or distances were stated, does not state finding original post. Therefore, cap left at orig. bearing and distance from original SW. BT and record. brg. from NW. original BT.

Fd. Ok by Ray Wytcherly - 10/2004 - M145-55