

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7603)

Set ¼ sec. post, from which
 A Pine 18" dia., bears N.55°W., 72 lks.
 A Pine 36" dia., bears S.20°E., 149 lks.
Built stone mound.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7681-82)

The ¼ sec. cor. nearly obliterated. No trace is found of the post, both bearing trees dead and one entirely destroyed by fire. I reestablish the cor. in its original position as follows:
Set a serpentine stone 12x10x8 ins., 8" in the ground for ¼ sec. cor., marked ¼ on W. face, from which
 A Cedar 12" dia., bears S.13½°E., 32 lks. dist. mkd. ¼ S10 BT.
 A Pine 12" dia., bears S.65°W., 47 lks. dist. mkd. ¼ S9 BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Aug. 1966 - C.S. File 54/28-63

Found - Stone at ¼ corner.
 12" Pine, down, S.65°W., 31.0 ft., found scribing "S9 BT".
 12" Cedar now 30", S.13½°E., 21.1 ft., shows old scar.
Set Brass cap at cor. mkd: County Surveyors Office
 T 31 S R 2 W
 ¼ S 9 | S 10
 1966
Reblazed and rescribed:
 30" Cedar S.13½°E., 21.1 ft. scribed ¼ S10 CS BT.
New BT - 13" Cedar N.39°W., 31.7 ft. mkd. ¼ S9 CS BT.