

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7604)

Set ¼ sec. post, from which
A Pine 18" dia., bears N.6°E., 37 lks.
An Oak 10" dia., bears S.22°W., 88 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - June 1961 - C.S. File 52/81-6

Found - Orig. 18" now 24" Pine, N.6°E., 24.4 ft., previously opened, shows good scribing "¼S".
Also find stump hole and remains of an Oak that checks bearing and distance for orig. SW. BT.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 2 W
¼ $\frac{S \ 3}{S \ 10}$
1961

New BT - 9" R.Fir bears S.31°W., 14.2 ft. scribed ¼ S10 CSBT

Survey by Glenn Baughman - For: U.S. Forest Service - March 1978 - M 65-69

Found - 1961 DCSO brass cap.
24" Pine, snag, bears N.6°E., 24.4 ft.
10" D.Fir bears S.31°W., 14.2 ft.
New BT - 12" D.Fir bears N.68°E., 9.6 ft. scribed ¼ S3 BT.

Douglas Co. Surveyors Office - Stephen J. Flause - Jennifer Heller - 8/26/2004 - C.S. File 67/10-2

Found - 2½" dia., brass cap (properly) marked on a 1¼" O.D. iron pipe is firmly set & protrudes approx. 10" above ground.
A Pine 18" now a fallen & rotted Pine snag approx. 26" dia., (no bark) with a previously opened blaze showing the scribing "¼ S3" bears N.6°E., 24.4 ft. (orig.)
A 9" R.Fir now 14" DBH D.Fir with a fully healed double blaze, bears S.31°W., 14.2 ft. (1961)
A 12" D.Fir now a 14" DBH D.Fir with a fully healed double blaze bears N.68°E., 9.6 ft. (1978)
New - A 35" DBH Ponderosa Pine scribed "¼ S10 CS BT" on a double blaze bears S.65½°E., 17.7 ft.
A 7" DBH D.Fir scribed "¼ S3 CS BT" on a double blaze bears N.29½°W., 10.8 ft.

continued next page

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Monument is in open older timber on a moderately steep east slope & approx. 700 ft. SSW from Northerly end of old drive able logging road
Comp dec. $16\frac{1}{4}^{\circ}$ E