

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; and S. 34, T30-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6753)

-----  
Set ¼ sec. post and built stone mound, from which  
    A Pine 40" dia., bears S.88°W., 158 lks.  
    A Pine 30" dia., bears N.86°W., 159 lks.  
Hon. Levi Scott's cabin bears SE. about 6 chains.

Survey by Glenn Baughman, PLS #536 - For: U.S. Forest Service  
March 1978 - M 65-69

-----  
Set 2" x 30" I.P. with brass cap stamped "T30S R2W WM 1/4 S34  
S3 T31S 1978 PLS 536"., from which  
    12" Pine bears S.28°W., 349.6 ft. scribed "¼ S3 BT".  
    12" double Cedar bears N.48°W., 38.0 ft. scribed "¼ S34  
    BT".

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - Crew,  
R.W. Smith - Wit: Paul Crum - Dec. 14, 1983 - C.S. File 62/13

-----  
INVESTIGATIVE REPORT ONLY

- Paul Crum, a property owner along this boundary asked that we look at the evidence he has found which he believes to be evidence of the monument set originally for the ¼ corner between sections 3 and 34.
- We first found the March 1978 Baughman survey monument, a 1½" brass cap on a 2½" iron pipe, protruding 14" above the ground. This monument was set at a proportionate position.
- At 133.7 ft. West of the Baughman monument, we were shown a mound of stone 24" dia. and 7" high. A metal post has been set down into the apparent opening of this mound. (The original survey notes call a wood post in a mound of stone at the corner position.)
- Checking for the orig. BTs revealed no evidence. The position of the 40" Pine, (S.88°W. 158 lks.) falls along the westerly edge of a road built for power line maintenance. The position of the 30" Pine, (N.86°W. 159 lks.) falls in the traveled way of the road. No conclusive evidence of either original bearing tree was located at the record positions from the mound of stone.
- The top soil in this area is shallow and rocky, the trees in this area do not mature to a size larger than the record bearing trees. There is also evidence of fire in this area.
- From the mound of stone, evidence of an old fence, barbed wire, wooden posts and nails, runs East to and beyond the monument set by Baughman. Fence evidence was also found funning North from the mound of stone.

(Cont. Next Page)

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 cor. for Sec. 3; and S. 34, T30-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

- As according to Mr. Crum, he located the stone mound after the Baughman survey monument was set. He indicated that the brush had to be cut away before the mound could be found. Mr. Crum first occupied this land in 1946. The old fence has been at the present location for a period of time prior to his time of residence.

- Accessories also found from Baughman monument: 12" Pine now 15" dia. bears S.28°W., 349.6 ft. A 12" Cedar now 14" dia. bears N.47°W., 28.0 ft.

Photos in C.S. File:

1. Rock mound and pipe as found.
2. Close up of mound and pipe, (note opening)
3. Stone mound with pipe removed.
4. Stone mound with metal pipe in background, old fence post, with nail, along side fence wire being held.
5. Mound of stone foreground, old fence post, with nail, being shown, orange witness sign to Baughman monument background.
6. Standing fence post being shown to the North.

Baughman corner Fd. OK, July 1994 by G. Baughman - M 120-69