

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7598)

Set ¼ sec. post, from which
A Laurel 8" dia., bears N.45°E., 5 lks.
A Laurel 10" dia., bears N.10°W., 9 lks.

C. E. Roberts - Wit: Jim Short; Chas. Patterson; Joe Renville
1902 - Field Book 6 Page 92

Start at NW. corner of Sec. 14, ran 40.30 S. Set 1/2" Miel
(?) Post, from which
An 18" Fir bears N.68°30'W., 8 lks.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones &
Terry Connell, crew - July 1966 - C.S. File 54/28-54

Found - Good 1/2" Iron pipe at ¼ corner.
18" Fir, now stump, N.68½°W., 5.3 ft., BT scribe
visible.
No trace of original BTs.
New BTs- 8" Cedar S.71°W., 8.0 ft. mkd. ¼ S14 CS BT.
9" Cedar S.54°E., 25.0 ft. mkd. ¼ S15 CS BT.
This corner lies by East and West fence line, 14" South of
fence line.

Douglas Co. Surveyors Office - Gregory Quibell; Karen Reed;
John Powell, crew - April 14, 1982 - C.S. File 61/30-23

Found - 1/2" I.P. protruding 18" out of ground.
8" now 14" Cedar with well healed double blaze bears
S.71°W., 8.0 ft.
9" now 13" Cedar with well healed double blaze,
bears S.52°E., 25.0 ft. (Rec. S.54°E.)
18" Fir stump with scribed "BT" visible, bears
N.68½°W., 6.0 ft. (Rec. 5.3 ft.)
At the location of the found 1/2" I.P., I SET a 1" x 30" I.P.
with brass cap attached mkd. "Douglas Co Surveyor T31S S15
S14 ¼ R2W 1982". I place 1/2" I.P. along South side of brass
cap. Due to rocky soil, I set I.P. with brass cap 8" into
the ground and build a mound of stone 18" tall around pipe.
New BTs- 10" Fir scribed "¼ S15 CS BT" in double blaze, bears
S.14°W., 15.9 ft.
13" Fir scribed "¼ S14 CS BT" in double blaze, bears
N.44°E., 42.0 ft.
(Sketch in C.S. File

FD. Ok by N. Hibbs, 8/2012 - M164-12A