

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7600)

Set ¼ sec. post, from which
A Pine 12" dia., bears N.2°W., 42 lks.
A Pine 30" dia., bears N.82°E., 74 lks.

H. L. Eppstein, Co. Surveyor - Wit: N.E. Richardson; G.A. Bachman; Harry Dourney - Oct. 5, 1928 - Vol. 3 Pg. 287

Set corner by placing same half way between section corner on line. This corner was gone. Old witness trees having been burned. Set stake and mound of rocks. Marked new witness trees as follows:
A 14" Fir S.35°E., 55 ft.
A 14" Cedar S.33°W., 36 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - Aug. 1966 - C.S. File 54/28-78

Found - 14" now 21" Fir, S.35°E., 55.0 ft., shows good scars.
14" now 17" Cedar, S.33°W., 38.0 ft., scribe marks visible.
Mound of stones destroyed.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 2 W
¼ S10|S11
1966
Bearing trees in good condition. Fence corner running N. and E. bears S.45°E., 4.4 ft.

Fd. and used in BLM resurvey by Donevan C. Harris, Cadastral Surveyor, under Group #755, surveyed Aug. 1971 - (DCSO records Vol. 38 Page(s) 14533-34)