

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 502300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26 & 27 only, (North)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7641)

-----  
Intersect E & W line 1.34 chs. East of the cor. of secs. 22, 23, 26 and 27. Set a basalt stone 15x8x6 ins., 10" in the ground for closing cor. of secs. 26 & 27 marked CC on S. with 2 grooves on S. and E. face, from which  
A Fir 36" dia., bears S.74°E., 26 lks. dist. mkd. T31S R2W S26 BT.  
A Fir 36" dia., bears S.27°W., 51 lks. dist. mkd. T31S R2W S27 BT.

Survey by John H. Markham, Jr. - March 26, 1952 - C.S. File 41/1-3

-----  
Both old BTs standing and in good shape.  
At corner point, found stone and drove Iron pipe.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - June/July 1966 - C.S. File 54/28-19

-----  
Found - 3/4" Iron pipe, 1.0 ft. long. This corner lies about 90.0 ft. East of corner to Secs. 22 & 23.  
Orig. 36" D.Fir now 45", S.74°E., 17.2 ft., tree opened for scribe.  
Orig. 36" D.Fir now 45", S.27°W., tree shows good scar.

Set Brass cap alongside I.P. mkd: County Surveyors Office  
T 31 S R 2 W  
S 23  
S 27 | S 26  
1966

No new BTs. All trees in good condition.  
This cor. lies about 90.0 east of 22|23/27

-----  
March 16, 1970 C.S. File 54/28-18  
Found 1966 Brass cap & mkd. new bearing trees:  
14" W.Fir S.77°W., 33.3 ft. scribed "T31S R2W S27 BT".  
10" D.Fir S.46½°E., 89.6 ft. scribed "T31S R2W S26 CS BT"  
This sec. corner lies 50.0 ft. West of logging road.