

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7593)

 Set post cor. secs. 25, 26, 35 and 36, from which
 A Fir 24" dia., bears N.45°E., 8 lks.
 A Fir 6" dia., bears S.8°E., 35 lks.
 An Oak 15" dia., bears S.30°W., 7 lks.
 An Oak 18" dia., bears N.46°W., 21 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7631-32)

The Sec. cor., which is nearly obliterated and bearing trees are deeply overgrown. I reestablish the cor. in its original position as follows:

A W.Oak 12" dia., for cor. of secs. 25, 26, 35 and 36, I mark T31S S25 on NE.; R2W S36 on SE.; S35 on SW.; and S26 on NW. side, with 1 notch on S. and E. sides from which
 A Fir 30" dia., bears N.35°E., 9 lks. dist. mkd. T31S R2W S25 BT.
 A Cedar 10" dia., bears S.60°E., 21 lks. dist. mkd. T31S R2W S36 BT.
 A W.Oak 20" dia., bears S.30°W., 8 lks. dist. mkd. T31S R2W S35 BT.
 A W.Oak 20" dia., bears N.45°W., 23 lks. dist. mkd. T31S R2W S26 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - June/July 1966 - C.S. File 54/28-28

 Found - No trace of W.Oak corner tree.
 10" Cedar, now 20", S.60°E., 13.9 ft., opened for scribe "BT".
 20" W.Oak now 26", S.30°W., 5.3 ft., shows good scar.
 30" D.Fir, now down, N.35°E., 5.7 ft., shows good scar.
 20" W.Oak, now snag, N.45°W., 15.2 ft.

Set Brass cap at cor. mkd: County Surveyors Office

T	31	S	R	2	W
S	26	S	25		
S	35	S	36		
				1966	

New BTs- 7" D.Fir N.52°W., 39.3 ft. mkd. T31S R2W S26 CSBT.
 8" D.Fir N.29°E., 27.0 ft. mkd. T31S R2W S25 CS BT

(Cont. Next Page)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by Glenn Baughman - For: U.S. Forest Service - July 1978 - C.S. File 58/173-3

Found - 1" I.P. with 2" brass cap 14" above ground.
A Cedar 22", bears S.60°E., 13.9 ft., good blazed face.
A W.Oak 26", bears S.30°W., 5.3 ft., good blazed face.
A D.Fir 36", bears N.35°E., 5.7 ft., now down, good blaze face.
A W.Oak snag 20", bears N.45°W., 15.2 ft., no face visible.
A D.Fir 10", bears N.29°W., 26.7 ft., good blazed face. (Rec. N.52°W., 39.3 ft.)
A D.Fir 10", bears N.62°E., 39.0 ft., good blazed face, now down. (Rec. N.29°E., 27.0 ft.)
A W.Fir 8", bears N.85°E., 35.9 ft.
Scribed- I scribed "T31S R2W S25 BT" on double blazed face of W.Fir 8", bears N.85°E., 35.9 ft.

Jonathan B. Drew, II, USFS - Assisted by: Jacob Hunt and Andrew Hillman - 5/15/2018 filed 5/14/2020 - C.S. File 65/106-17

Found - A 1½" IP with a 2½" brass cap, projecting 8" above the ground.
A root hole bears, N.30°45'E., 4.3 ft, a rotted fir log lays east. (N.45°E., 5.28' 1857) (N.35°E., 5.94 ft 1906, 5.7 ft 1966, 1978)
No trace found of (1857)6" Fir.
A root hole bears, S.42°15'W., 4.7 ft. a rotted Oak log lays SE. (S.30°W., 4.62 ft 1857) (5.28 1906, 1966, 1978)
A rotted oak snag bears, N48°15'W., 15.8 ft, with no marks visible. (N.46°W., 13.86 ft 1857) (N.45°W., 38.8 ft. 1906, 1966, 1978)
A root hole bears, S.47°15'E., 11.2 ft. a cedar log lays NE. (S.60°E., 13.86 ft 1906,1966,1972,1978)
A 20" Fir bears, N.27°W., 26.7 ft, with a healed double blaze. (N.52°W., 39.3' 1966, (38.8' 1972) (N.29°W., 26.7' 1978)
No trace found of a (1966)8" Fir.
A rotted stub bears, N.83°E., 34.0 ft. with no marks visible (N.85°E., 35.9' 1978).
Guard post(s): South - 4.5 ft
New - A 16" Oak bears, S.56°45'W., 23.6 ft mkd "T31SR2WS35" "BT" on a double blaze.

Continued next page

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 6" cedar bears, S.29°E., 39.5 ft mkd "X" "BT" on a double blaze.
A 10" ash bears, N.50°45'E., 47.6 ft, barked scribed "T31SR2WS25BT"
New BTs include a 3/4" brass washer marked "OR PLS 89396" nailed flush in the lower blaze between the "B" & "T" marks.
Corner maintenance/other info -
Clear brush from around monument & to BTs, BT faces & a 6" band at head height painted red. Add new nails to BT tags & add new tags where needed.
monument sizes are outside diameter & BT diameters are at breast height.
*Note - Line maintained SOUTH -1/4 mile.
NFSL lines bear: (1972) S.89°57'15"E., 2673.23 ft & (1906) S.0°01'E., 2640.00 ft
GEODETIC COORDINATES -
LATITUDE: N.42°50'35.746" LONGITUDE: W. 122°54'11.578"
DATUM: WGS84