

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7593)

-----  
Set ¼ sec. post, from which  
A Fir 36" dia., bears N.18°W., 38 lks.  
An Oak 6" dia., bears East, 7 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May 10, 1906 - (DCSO records Vol. 18 Page(s) 7672)

-----  
The ¼ sec. cor. nearly obliterated. One bearing tree standing, the only remaining evidence of the corner. I reestablish the cor. in its original position as follows:  
Set an ironstone 15x12x10 ins., 10" in the ground for ¼ sec. cor. mkd. ¼ on W. face, from which  
A Fir 10" dia., bears S.86°E., 20 lks. dist. mkd. ¼ S25 BT.  
A Fir 12" dia., bears S.70°W., 20 lks. dist. mkd. ¼ S26 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Terry Connell, crew - June/July 1966 - C.S. file 54/28-22

-----  
Found - No trace of corner stone.  
Orig. 10" W.Fir now 15", S.86°E., 13.2 ft. tree dead.  
Orig. 12" W.Fir now 18", S.70°W., 13.2 ft., opened for scribing. This tree is dying.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 2 W  
¼ S26|S25  
1966  
New BTs- 10" W.Fir N.11°E., 25.1 ft. scribed ¼ S25 CS BT  
13" D.Fir N.88°W., 55.0 ft. scribed ¼ S26 CS BT  
This corner lies in cut unit about 140 ft. South of old logging road.

Fd. OK, Aug. 1972 by W.S. Barnes - M 42-69