

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & S. 36, T30-2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6754)

-----  
Set ¼ sec. post, from which  
    An Oak 24" dia., bears N.72°W., 88 lks.  
    A Pine 50" dia., bears S.55°E., 30 lks.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy - A. Victor Cangie; D. Stewart, crew - April 22, 1976 - C.S. File 59/8-22

-----  
Found - Remains of an orig. BT, a 50" Pine, now a hollow, burnt and rotting stump. After a diligent search, we find a well preserved piece of wood with good scribing "BT" visible. This piece of wood was found at the base of the stump.

We also find a hollow Oak snag at the proper location for the orig. NW. BT, however, we find no evidence of corner marking.

At the true corner point as determined by the record bearing and distance from the aforementioned remains of the orig. SE. BT, an orig. 50" Pine now a badly deteriorated stump, bearing S.55°E., 19.8 ft. from the cor. point:

SET a 1" x 30" I.P., 25" in the ground with brass cap attached marked: Douglas County Surveyor 1976

T 30 S R 2 W

¼  $\frac{S\ 36}{S\ 1}$

We find no trace of the original corner monument.  
New BTs- A 9" D.Fir bears N.75°W., 60.9 ft. scribed "¼ S36 CS BT" on a double blaze.

A 15" D.Fir bears S.2½°E., 50.7 ft. scribed "¼ S1 CS BT" on a double blaze.

We deposit the found scribing at the base of the Pine stump. A fence corner of nearly new fences running South and East bears S.36°W., 58.0 ft.

Troy Rambo - For: Seneca Jones Timber Co. & Roseburg Resources Co. - 6/2010 - M160-77

-----  
Found - 1976 DCSO BC & BTs per C.S. 59/8  
    A steel fence post with a USFS sign, bears N.85°W., 3.2 ft.  
    A alum. post with a USFS sign, bears S.4°W., 3.3 ft.  
    A fence corner bears 1 ft. West.

continued next page

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & S. 36, T30-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Jonathan B. Drew, II, USFS - Assisted by: Andrew Hillman -  
6/10/2015 - C.S. File 65/90-70

-----  
Found - A 2½" brass cap on a 1½" galvanized iron pipe,  
projecting 7" above the ground.  
An indeterminate size Oak stub with no marks visible  
(N.72°W., 58.1') 1857  
An indeterminate size pine stump with AX work  
visible. (S.55°E., 19.8') 1857  
26" Fir with healed double blaze. (N.75°W. 60.9') 1976  
28" Fir with healed single blaze. (S.2°30'W. 50.7') 1976  
No new accessories added - No new measurement taken  
Note - Clear brush from around monument and to BTs. Tie  
flagging to monument and guard posts, paint BT  
faces & a 6" band at head height, add new nails  
to existing BT tags & add new tags where needed.  
Lat: N 42°54'59.663" Long: W 122°53'34.884"  
Ellipsoid Height: 3010 ft.  
Datum: WGS84  
Source: Cell phone GPS, for navigation to corner.