

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19, T31-1

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7458)

 Set post, cor. secs. 13, 24, 18 and 19, from which
 An Ash 18" dia., bears N.77°W., 114 lks. dist.
 An Ash 18" dia., bears S.1°E., 300 lks. dist.
 A Pine 18" dia., bears N.40°E., 82 lks. dist.
 A Pine 15" dia., bears S.30°W., 150 lks. dist.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - Wit: N.E. Richardson; B.A. Lane; F.L. Thomas - Jan. 1931 - M 1-38

 Position identified from Orig. BT:
 Oak N.77°W., 114 lks.
 Stump of Pine, N.40°E., 82 lks.
 (Original notes call for 2 Ash BTs. One is Oak mentioned above and other must have been an Oak as there has never been Ash on spur.)
 Set rock 6" x 10" x 18", 16" in ground for corner, from which
 A 14" B.Oak N.42°E., 131 lks. "T31S R1W S18 CS BT".
 A 20" B.Oak N.65½°W., 67 lks. "T31S R2W S13 CS BT".
 A 20" Madrona S.56°W., 27 lks. "T31S R2W S24 CS BT".
 An 18" Fir S.10°E., 150 lks. "T31S R1W S19 CS BT".

Douglas Co. Surveyors Office - John M. Powell, Frank Jones; Terry Connell, crew - July 1966 - C.S. File 54/28-39

 Found - Stone at section corner, 16x10x8.
 20" B.Oak N.65½°W., 44.2 ft. Opened for scribe "3BT". Rotten. (Brg. should be N.75½°W.)
 No trace of NE. or SE. BTs.
 20" Laurel now 24", S.56°W., 17.8 ft., no scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office

R	T	31	S	R
2	S	13	S	18
W	S	24	S	19

1966

New BTs- 24" Cedar N.45½°W., 11.9 ft. scribed T31S R2W S13 CS BT.
 14" D.Fir N.2½°W., 22.9 ft. scribed T31S R2W
 10" D.Fir S.45°E., 39.4 ft. scribed T31S R1W S19 CS BT.

Reblazed and rescribed:
 24" Laurel S.56°W., 17.8 ft. scribed T31S R2W S24 CS BT.