

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 979020

PRIMARY CORNER DESCRIPTION Cor. No. 3 Mill site No. 1 (MS)

Alias _____ Description Cor. No. 2 Mill Site No. 2 (MS)

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

BLM Mineral Survey No. 975 A&B, surveyed by Walter L. Gonnason, Mineral Surveyor, surveyed March/Sept. 1963: Mineral Survey canceled per BLM letter dated 6/15/2000 - (DCSO records Vol. 38 Page(s) 15700)

Cor. No. 3 on east-west center sec. line, previously stated identical with Cor. No. 2, Mill Site No. 2 of this survey.

Set a pipe, 1/2" dia., 24" long, 18" in the ground, with 3" dia. brass cap, mkd. 975B MS 1 3 MS 2 2; from which A cedar, 8" dia., bears S.83°W., 24.3 ft., mkd. 975B MS 1-3 BT.

A cedar, 6" dia. bears S.48°W., 9.4 ft. mkd 975B MS 2-2 BT
Magnetic declination 20°00'E.