

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 979040

PRIMARY CORNER DESCRIPTION Cor. No. 4 Mill Site No. 2 (MS)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey No. 975 A&B, surveyed by Walter L. Gonnason, Mineral Surveyor, surveyed March/Sept. 1963: Mineral Survey canceled per BLM letter dated 6/15/2000 - (DCSO records Vol. 38 Page(s) 15701)

Set a pipe, 1/2" dia., 4" long, 18" in the ground, with 3" dia. brass cap, mkd. 975B MS 2 4; from which

A fir, 38" dia. bears N.34°W., 12.7 ft. mkd 975B MS 2-4 BT

A fir, 26" dia. bears S.10°W., 24.9 ft. mkd 975B MS2-4 BT

Magnetic declination 20°30'E.