

TOWNSHIP 31 RANGE 02 POINT IDENTIFIER # 979060

PRIMARY CORNER DESCRIPTION Cor. No. 4 Mill Site No. 1 (MS)

Alias _____ Description Cor. No. 1 Mill Site No. 2 (MS)

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

BLM Mineral Survey No. 975 A&B, surveyed by Walter L. Gonnason, Mineral Surveyor, surveyed March/Sept. 1963: Mineral Survey canceled per BLM letter dated 6/15/2000 - (DCSO records Vol. 38 Page(s) 15701-2)

Cor. No. 4, identical with Cor. No. 1 Mill Site No. 2 of this survey.

Set a pipe, 1/2" dia. 24" long, 18" in the ground, with 3" dia. brass cap, mkd. 975B MS 1 4 MS 2 1; from which
A hemlock, 12" dia., bears N.6°E., 26.3 ft., mkd. 975B M1-4 BT.

A Fir, 25" dia. bears N.47°E., 16.7 ft. mkd 975B MS 2-1 BT
Magnetic declination 20°30'E.