

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7772)

Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on N. face; from which

A Fir 11" dia., bears N.50¼°E., 20 lks. dist. mkd. ¼ S BT.

A Fir 24" dia., bears S.22°E., 52½ lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Jan. 1966 - C.S. File 52/63-58

Found - 11" D.Fir now 20", N.50°E., 13.2 ft., opened tree for scribe "S".

24" Fir snag, tree rotted out S.22°E., 34.6 ft.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 3 W

¼ $\frac{S}{S}$
5
8

1966

New BTs- 10" Laurel S.33°E., 30.4 ft. scribed ¼ S8 CS BT.

10" Laurel N.59½°W., 10.0 ft. scribed ¼ S5 CS BT.