

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7753)

Set a stone 14x10x4 ins., 10" in the ground, for 1/4 sec. cor. marked 1/4 on N. face; from which

A Laurel 8" dia., bears N.70°W., 45 lks. dist., mkd. 1/4 S BT

A Laurel 10" dia., bears S.69°E., 36 1/2 lks. dist., mkd. 1/4 S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, Mike Stone, Jack Heritage, crew - April 1966 - C.S. File 52/63-91

Found - No trace of corner stone.

10" Laurel, now 16", S.69°E., 24.1 ft. Opened this tree for "1/4" done with axe. By ring count, it is done about the time of original survey. Good distance on call from top of ridge. Also, very old cruising marks around corner.

No trace of 8" Laurel N.70°W., 29.7 ft.

Set 5/8" Iron rod at 1/4 corner.

New BTs- 8" Cedar N.31°E., 11.3 ft. scribed 1/4 S16 CS BT.

11" D.Fir S.54°W., 9.0 ft. scribed 1/4 S17 CS BT.