

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec Cor for 8, 9, 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7754)

Set a stone 10x10x8 ins., 7" in the ground, for cor. to secs. 8, 9, 16 and 17, marked with 4 notches on E. and S. edges; from which

A Cedar 28" dia., bears N.8°E., 23½ lks. dist. mkd. T31S R3W S9 BT.

A Cedar 28" dia., bears S.21½°E., 59 lks. dist. mkd. T31S R3W S16 BT.

A Cedar 28" dia., bears S.23½°W., 43 lks. dist. mkd. T31S R3W S17 BT.

A Fir 16" dia., bears N.23 3/4°W., 8¼ lks. dist. mkd. T31S R3W S8 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, Mike Stone, Jack Heritage, crew - April 1966 - C.S. File 52/63-94

Found - 28" Cedar now 36", S.23½°W., 28.4 ft., burnt face and scribe visible.

28" Cedar now 37", N.8°E., 15.2 ft., shows good scar

28" Cedar now 35", S.21°E., 38.9 ft., shows good scar.

16" Fir now 26", N.23 3/4°W., 5.9 ft., shows good scar.

No trace of corner stone.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 3 W

S 8 | S 9

S 17 | S 16

1966

Rescribed and reblazed:

36" Cedar S.23½°W., 28.4 ft. mkd. T31S R3W S17 CS BT