

PRIMARY CORNER DESCRIPTION NE Cor. Lot 9, Section 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: R.G. Boyd - June 20, 1960 - C.S. File 42/392-61

At corner point, Set 1½" x 36" I.P., from which
14" Cedar N.84°E., 22.2 ft. "1/16 S3 R3W BT"
14" Maple N.13°E., 27.8 ft. "1/16 S3 X BT"
22" Alder S.23°W., 32.0 ft. mkd. "1/16 S4 BT"
Road bears North 285.0 ft.
Stouts Creek bears North 50.0 ft.
1/4 Cor Secs. 3 & 4 bears South 1251.0 ft.

Douglas Co. Surveyors Office - M. Lenora Ladig; J. Cook;
Karen Cheney, crew - June 9, 1976 - C.S. File 59/15-13

Found - 1½" x 36" I.Pipe, loose and protruding 28" above
ground.
A 14" now 18" Cedar bears N.84°E., 22.2 ft. Tree
alive with well healed double blaze.
A 14" now 17" Maple bears N.13°E., 27.8 ft. Tree
alive with "1/16 S3 X BT" visible in healed
double blaze.
A 22" Alder bears S.23°W., 32.0 ft. Tree alive with
"1/16 S4" in healing double blaze.

At true corner point, Set a 1" x 36" I.Pipe with brass cap
mkd: Douglas Co. Surveyor

T31S R3W	
Lot	Lot S
S 8	5 3
4 Lot	Lot
9	12
1976	

Placed 1½" I.Pipe on North side of cap.
Corner lies approx. 50 ft. East of the West for of Stouts
Creek. Corner also lies approx. 280 ft. East of Rd. #31-3-
3.2 which is a summer road only.

Douglas Co. Surveyors Office - R.B. Kimberling; M.W. Cline,
crew - Oct. 3, 1977 - C.S. File 59/40-30

Found - A 5/8" I.R. with 2" alum. cap set 6" above ground
and mkd. "T31S R3W N 1/16 S4 S3 LS 498" with an
18" mound of stone to top of cap.
A 1" x 36" I.P. with brass cap set 2" above ground
mkd. "Douglas County Surveyor T31S R3W Lot 8 Lot
5 Lot 9 Lot 12 S4 S3 1976"
A 1½" x 36" I.P. at North edge of brass cap set 6"
above ground.

(Cont. Next Page)

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 400660

PRIMARY CORNER DESCRIPTION NE Cor. Govt. Lot 9, Sec. 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

All bearings and distances are from 2" alum. cap.

Accessories found:

14" now 16" Cedar bears N.65°E., 38.3 ft. with visible scribe marks in almost healed blaze.

14" now 16" Maple bears N.25°E., 45.8 ft. with scribing "1/16 S3 BT" in partly healed double blaze.

22" now 18" Alder bears South 14.1 ft. with visible scribing "1/16 S4 T" in rotting double blaze.

No new monument set.

Removed DCS0 brass cap to recognize alum. cap set by Johnstone in survey filed as M 65-41. BLM has confirmed 1½" I.P. of prior survey is doubtful.

Tony Hostetter - For: Rome Crk Timber - Sept. 2015 - M170-20

Found - 1½" iron pipe, cap is gone set by Johnstone in 1977 (M65-41). Also described in 1982 (M92-44).

13" burnt maple, bears N.25°E., 45.8 to center.

30" cedar, bears N.65°E., 38.2 to center.