

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7743)

Set stone 10x10x6 ins., 6" in the ground for 1/4 sec. cor. marked 1/4 on N. face; from which

A Laurel 6" dia., bears S.86 1/2°W., 33 1/2 lks. dist. mkd. 1/4 S BT.

A Laurel 6" dia., bears N.87°W., 33 1/2 lks. dist. mkd. 1/4 S BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #555, surveyed July/Aug 1964 - (DCSO records Vol. 33 Page(s) 13827-28)

The 1/4 sec.cor., monumented with the original basalt stone, 10x10x5 ins., loosley set 5" in the ground, mkd. 1/4 on N. face, from which the remains of the original bearing trees:

A down and rotted Madrone 10" dia., bears N.20°W., 18 lks., with fragmentary scribe marks visible on fragments of overgrowth, tree has been displaced and original position is indeterminate. (Rec. brg. & dist., S.86 1/2°W., 33 1/2 lks.)

A down and rotted Madrone 10" dia., bears N.87°W., 31 lks. dist., with fragmentary scribe marks visible on opened blaze. (Rec. dist. 33 1/2 lks.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 23" in the ground, with brass cap mkd:

T 31 S R 3 W
1/4 S 10
 S 15
 1964

from which new bearing trees:

A Fir 18" dia., bears N.17°W., 22 lks. dist. mkd. 1/4 S10 BT.

A Fir 17" dia., bears S.62°W., 9 1/2 lks. dist. mkd. 1/4 S15 BT.

Reset original corner stone alongside the iron post.

Corner is located at the head of a ravine, drains N.85°E.

BLM Dependent resurvey, rehabilitation, & renumeration by A. Bert Skeesick, Cadastral Surveyor, and Robert H. Browning, Surveying Tech., under Group No. 2000, 2100, 2300 - Surveyed Aug. 2005/Feb. 2006 - (DCSO records Vol. 55 Page 21618 & 2009 BLM Plat)

Latitude 42°53'09.96"N
Longitude 123°02'33.58"W (NAD 1983 (CORS))