

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7727)

-----  
Set a stone 17x10x8 ins., 11" in the ground for ¼ sec. cor. marked ¼ on W. face; from which  
A Fir 30" dia., bears S.34°E., 14 lks. dist. mkd. ¼ S BT.  
A Cedar 28" dia., bears N.67°W., 48½ lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - Nov. 18, 1959 - C.S. File 42/392-41

-----  
Determined by O.B.Ts:  
34" Fir snag, S.34°E., 9.2 ft.  
40" Cedar N.67°W., 31.6 ft.  
At corner point found large stone and Set 1/2" x 24" iron pipe from which  
4" Fir S.72°E., 25.0 ft. mkd. ¼ S14 BT.  
6" Fir S.54°W., 18.6 ft. mkd. ¼ S15 BT.  
8" Fir N.64°W., 19.1 ft. mkd. ¼ S15 X BT.  
9" Fir N.28°W., 33.8 ft. mkd. ¼ S15 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Dec. 1965 - C.S. File 52/63-31

-----  
Found - 1/2" I.Pipe and stone at ¼ corner.  
34" D.Fir stump, S.34°E., 9.2 ft., orig. BT, shows good scar.  
40" Cedar N.67°W., 31.6 ft., orig. BT. Bearing should be N.69°W.  
No trace of S.72°E. Fir.  
6" Fir now 8", S.54°W., 18.6 ft., shows good scars.  
8" Fir now 10", N.64°W., 19.1 ft. shows good scars.  
9" Fir now 11", N.28°W., 33.8 ft. shows good scars.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 3 W  
¼ S15 | S14  
1965

Set alongside 1/2" iron pipe.  
New BT - 6" Fir S.89°E., 39.6 ft. scribed ¼ S14 CS BT.