

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by William Bushey, Deputy Surveyor, under remonumentation #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7729)

Set a Cedar post, 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on W. face; from which
A Laurel 17" dia., bears S.75 1/2°W., 29 lks. dist. mkd. 1/4 S BT.
A Laurel 12" dia., bears N.42 1/2°E., 44 1/2 lks. dist. mkd. 1/4 S BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #555, surveyed July/Aug 1964 - (DCSO records Vol 33 Pages 13825-26)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 31 S R 3 W
1/4
S 10 | S 11
1964

from which
A Fir 21" dia., bears S.38 3/4°E., 57 lks. mkd. 1/4 S11 BT.
A Fir 15" dia., bears N.32°W., 31 lks. mkd. 1/4 S10 BT.
Corner is located on a spur, slopes S.60°W.

BLM Dependent resurvey, rehabilitation, & remonumentation by A. Bert Skeesick, Cadastral Surveyor, and Robert H. Browning, Surveying Tech., under Group No. 2000, 2100, 2300 - Surveyed Aug. 2005/Feb. 2006 - (DCSO records Vol. 55 Page 21618 & 2009 BLM Plat)

The 1/4 sec. cor. of secs. 10 & 11 monumented with an iron post, 2 1/2" dia., firmly set, projecting 1" above ground, with brass cap mkd. as reported by Jelley in 1964; from which the remains of a BT mkd. by Jelley
A sawed burnt fir stump, 20" dia., bears N.28 1/2°W., 21.9 ft. with scribe marks 1/4 visible on an open blaze. (Rec. N.32°W., 20.5 ft.)
and new BTs
A madrone, 5" dia., bears S.70 1/2°E., 10.0 ft., mkd: 1/4 S11 BT in the bark.
A madrone, 4" dia., bears N.1 1/2°W., 16.0 ft., mkd: 1/4 S10 BT in the bark.
Corner is located 63.0 ft. North of a graveled road, 15 ft. wide, which bears N.63°E., & S.59°W.