

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7708)

-----  
Set a stone 15x10x10 ins., 10" in the ground for cor. to secs. 23, 24, 25 and 26, marked with 1 notch on E. and 2 notches on S. edges; from which

A Hemlock 6" dia., bears N.28 3/4°E., 38 lks. dist. mkd. T31S R3W S24 BT.

A Hemlock 6" dia., bears S.79°E., 23½ lks. dist. mkd. T31S R3W S25 BT.

A Fir 40" dia., bears S.78°W., 34½ lks. dist. mkd. T31S R3W S26 BT.

A Fir 28" dia., bears N.43°W., 64½ lks. dist. mkd. T31S R3W S23 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - Dec. 16, 1959 - C.S. File 42/392-48

-----  
Determined by O.B.T.s:

56" Fir S.78°W., 22.4 ft.

10" hemlock N.29°E., 25.0 ft.

12" Hemlock S.79°E., 15.2 ft.

At corner point, found stone and set 1½" x 30" Iron pipe, from which

11" Hemlock N.45°W., 10.4 ft. "S23 BT"

7" Hemlock S.7°W., 5.2 ft. "S26 BT".

7" Hemlock S.67°E., 15.0 ft. "S25 R3W BT".

David Edwards - For: Rome Creek Timber LLC - 9/2015 - M169-68

-----  
Found - 1½" dia. iron pipe per C.S. 42/392.

13" hemlock N.29°E., 26.4'

21" hemlock S.79°E, 15.7'

15" hemlock S.7°W, 5.2'

All with healed blazes and badly burned.

No live trees within 400 feet