

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7710)

Set a stone 18x8x8 ins., 12" in the ground, for 1/4 sec. cor. marked 1/4 on W. face; from which
A Laurel 8" dia., bears N.32°W., 49 lks. mkd. 1/4 S BT.
A Laurel 8" dia., bears S.29°E., 82 lks. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - Dec. 16, 1959 - C.S. 42/39249

Determined by O.B.T.s:
14" Laurel N.32°W., 32.3 ft I rescribed "1/4 S23 T31S R3W BT"
At corner point, found stone and Set 1/2" x 30" Iron pipe, from which
7" Laurel N.52°E., 12.0 ft. "1/4 S24 R3W BT".
15" Pine, East 7.0 ft. "1/4 S24 BT".
8" Laurel S.67°E., 11.7 ft. "1/4 S24 BT".
7" Laurel S.35°W., 5.0 ft. "1/4 S23 R3W BT".

Survey by Malcolm Clark - For: U.S. Forest Service - April 1980 - C.S. File 58/227 (n) and M 83-53

Found - 3/4" x 24" Iron pipe with possible original stone alongside.
18" Madrone bears N.30°51'W., 32.1 ft. with good scars.
9" Madrone bears N.50°04'E., 12.3 ft. with good scars.
24" Pine bears N.87°51'E., 7.0 ft. with good scars.
12" Madrone bears S.69°02'E., 11.6 ft. with good scars.
8" Madrone bears S.30°21'W., 4.8 ft. with good scars.
18" Madrone bears S.29°18'E., 52.8 ft. Possible original BT., another very rotten tree is close to this one.
Set 2" x 30" alum. pipe with 2 1/2" alum. cap mkd: "T31S R3W 1/4 S23 & S24 PLS 866 1980".
Replaced 3/4" x 24" Iron pipe on West side of alum. pipe.

Fd. OK, April 1981 - See BLM for administrative survey

Gerald Nygren - For: Roseburg Resource Co. - 9/2015 - M170-10

Found - 2 1/2" alum. cap & BTs
18" madrone bears N.30°51'W., 32.1' burnt with healed face, tag dated 1980 (1893) cont.

