

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7715)

-----  
Set a stone 18x12x3 ins., 12" in the ground, for cor. to secs. 1, 2, 11 and 12, marked with 1 notch on E. and 5 notches on S. edges; from which

A Fir 34" dia., bears N.45¼°E., 76 lks. dist. mkd. T31S R3W S1 BT.

A Fir 24" dia., bears S.60°E., 80 3/4 lks. dist. mkd. T31S R3W S12 BT.

A Cedar 12" dia., bears S.33½°W., 54 3/4 lks. dist. mkd. T31S R3W S11 BT.

A Fir 30" dia., bears N.4°W., 45¼ lks. dist. mkd. T31S R3W S2 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R. G. Boyd - May 4, 1959 - C.S. File 42/392-17

-----  
Determined by O.B.T.s:

40" Fir N.45°E., 52.0 ft.

32" Fir S.60°E., 53.3 ft.

24" Cedar S.35°E., 35.6 ft., found scribe.

48" Fir N.6°W., 31.4 ft.

At corner point, found stone, from which

8" Laurel bears N.69°W., 11.7 ft. mkd. S2 T31S R3W BT.

8" Laurel bears N.59°E., 19.4 ft. mkd. S1 BT.

8" Laurel bears S.75°E., 26.0 ft. mkd. S12 BT.

8" Laurel bears S.47°W., 22.0 ft. mkd. S11 T31S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Dec. 8, 1965 - C.S. File 52/63-15

-----  
Found - I.Pipe and stone at sec. corner.

8" now 9" Laurel, N.69°W., 11.7 ft., scribe visible.

8" now 11" Laurel N.59°E., 19.4 ft., scribe visible.

8" now 10" Laurel S.75°E., 26.0 ft. scribe visible.

8" now 9" Laurel S.47°W., 22.0 ft., scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 3 W

S 2 | S 1

S 11 | S 12

1965

All BTs renewed by Markham in good shape.

continued next page

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - For: Roseburg Resources Co - Jan. 2015 - M166-29

-----  
Found - Brass cap per 1965 Douglas Co. Surveyor's Office renewal.

- 44" Fir N.46°E., 50.0' healed scar.
- 43" Fir N.5°W., 29.2' healed scar.
- 15" Madrone N.59°E., 17.7' healed scar.
- 11" Madrone N.65°W., 11.6' healed scar.
- 9" Madrone S.45°W., 21.3' healed scar.
- 14" Madrone S.75°E., 25.9' healed scar.
- 36" Cedar S.34°W., 34.6' healed scar.

See M166-29 for information, all trees are badly burnt. Added 60D spike to side/center at base of all trees by R Quimby; Area badly burnt 8/2015 - C.S. File 65/89-30  
Hand held Lat & Long: N. 42°54.060 W.123°00.801