

TOWNSHIP 31 RANGE 03 POINT IDENTIFIER # 607700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only, T30-3

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6775)

Set a stone 16x14x8 ins., 12" in the ground for ¼ sec. cor. marked ¼ on N. face, from which

A Fir 6" dia., bears S.47¼°E., 19 lks. dist. mkd. ¼ S BT.

A Cedar 6" dia., bears N.77½°E., 29 lks. dist. mkd. ¼ S BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Dec. 1965 - C.S. File 52/63-25

Found - No trace of stone.

6" now 9" Cedar N.77½°E., 19.1 ft. Had been opened for scribe "¼".

6" now 12" Fir S.47¼°E., 12.5 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W ¼ S 36

1965

Both trees original and in good shape. No need for new BTs.

Ron Quimby - Crew: N. Fromdahl & L. Heddens - 6/2020 - C.S. File 65/106-32

Found - DCSO brass cap (properly mkd)

Both Orig. BTs are rotted stumps

New - 6" W.Fir N.12°E., 8.2 ft. scribed ¼ S36 BT

14" Fir S.23°E., 5.0 ft. scribed ¼ S36 BT

8" Fir S.48°W., 10.6 ft. scribed ¼ S36 BT

6" Fir N.13°W., 12.2 ft. scribed ¼ S36 BT

Note - Compass decl. 15½°E.