

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 100176

PRIMARY CORNER DESCRIPTION E. Sec. Cor. for 25 & 36 only, T31-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Butler Ives and Geo. Hyde under Contract #39 dated Jan. 4, 1854 (DCSO records Vol. 18 Page(s) 7780)

-----  
Set post, cor. of secs. 30, 31, 25 and 36, from which  
A Fir 16" dia., bears N.54°W., 31 lks.  
A Fir 24" dia., bears S.36°W., 35 lks.  
A Fir 18" dia., bears S.32°E., 41 lks.  
A Fir 16" dia., bears N.50°E., 45 lks.

GLO survey by Wm. M. Bushey, under Contract #620 dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7851-52 & 7854)

-----  
Intersect the W bdy. of the tp.(T31-4) 3.70 chs. N of the cor. to secs. 25, 30, 31, and 36, which is a post, greatly decayed, with marks obliterated, from which  
A Fir 16" dia., (24" now) bears N.50°E., 45 lks. dist., marked T31S R4W S30 BT.  
A Fir 18" dia., (30" now) bears S.32°E., 41 lks. dist., marked T31S R4W S31 BT.  
A Fir 24" dia., bears S.36°W., 35 lks. dist., marked T31S R5W S36 BT.  
A Fir 16" dia., (24" dia.) bears N.54°W., 31 lks. dist., marked T31S R5W S25 BT.

The old cor. established for secs. 25, 30, 31 and 36, is not a cor. to secs. 30 and 31. I, therefore, destroy the marks on the 2 Fir witness trees E. of the old cor. in T31S R4W, and remove post cor. which is greatly destroyed, and set a stone, 14x8x7 ins., 10" in ground, for cor. to secs. 25 and 36, marked with 5 notches on N and 1 notch on S faces.

Douglas Co. Surveyors Office - John Powell; Frank Jones; Joe Brady - March 1966 - C.S. File 54/20

-----  
Found - 24" Fir now stump, N.54°W., 20.5 ft., "BT" scribe visible.  
24" Fir now dead snag, S.36°W., 23.1 ft. shows good scar.  
30 Fir now 38", S.32°E., 27.1 ft. shows scar.  
24" Fir now dead snag, N.50°E., 29.7 ft. shows scar.  
No trace of stone at sec. corner.

Set Brass cap at sec. cor. mkd: County Surveyors Office

R	T 31	S	R
5	S 25	31	4
W	S 36		W

1966

New BTs -51" D.Fir N.60°E., 49.0 ft scribed T31SR4W S31 CS BT  
12" Cedar S.51°E., 51.5 ft scribed T31S R4W S31 CSBT

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 100176

PRIMARY CORNER DESCRIPTION E. Sec. Cor. for 25 & 36 only, T31-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15642-43)

-----  
The sec. cor., perpetuated by Powell in 1966, monumented with an iron post, 1½" dia., firmly set, protruding 10" above ground with brass cap marked: County Surveyors Office

T 31 S R 4 W  
S 25 | S 31  
S 36 |  
R 5 W |  
1966

- from which the remains of the original bearing trees:
- A Fir snag 29" dia, bears N.50°E., 45 lks. dist., with healed blaze. (Marks reported destroyed by Bushey, in 1894)
  - A Fir 40" dia., bears S.32°E., 41 lks. dist., with healed blaze. (marks reported destroyed by Bushey in 1894)
  - A Fir snag 30" dia., bears S.36°W., 35 lks. dist., with healed blaze.
  - A Fir stump 30" dia., bears N.54°W., 31 lks. dist., with scribe marks BT visible on opened blaze.
- and bearing trees mkd. by Powell:
- A Cedar 16" dia., bears S.51°E., 77 lks. dist. with scribe marks T31S 4W 3 visible on partially healed blaze.
  - A Fir snag 52" dia., bears N.60°E., 75 lks. dist., with healed blaze.
- and new bearing trees:
- A Fir 4" dia., bears S.16°W., 10 lks. dist., mkd. X BT.
  - A Fir 6" dia., bears N.6°W., 30 lks. dist. mkd. T31S R5W S25 BT.

1966 County brass cap, 4 orig. BTs, 2 County BTs and 2 1972 BTs, Fd. OK, BLM survey by Rogers, McMullen and Bishop under Group #1217, 1984-86 (DCSO records, Vol. 47 Pg. 18134)