

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 100434

PRIMARY CORNER DESCRIPTION W 1/4 Cor. for Sec. 13 only, T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and Geo. Hyde under Contract #39 dated Jan. 4, 1854 (DCSO records Vol. 18 Page(s) 7778)

Set ¼ sec. post, on W point of a ridge, from which
A Fir 8" dia., bears S.73°W., 15 lks.
A Laurel 10" dia., bears S.71°E., 41 lks.

GLO survey by Wm. M. Bushey, under Contract #620 dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7867)

Set temp. post. The ¼ sec. cor. is gone. I find 1 witness tree at cor. point.
Set a stone, 14x12x9 ins. 10" in the ground, for ¼ sec. cor. marked ¼ on W face; from which
A Fir 8" dia., (12" now) bears S.73°W., 15 lks. dist., marked ¼ S BT.
Fire has destroyed the Laurel in Sec. 18. I therefore mark
A Laurel 7" dia., which bears N.34°E., 29 lks. dist., ¼ S BT.

BLM resurvey by Berry and Akin, under Group 800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15647-48)

Point for the ¼ sec. cor. of sec. 13 only, determined by the method of irregular boundaries, there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
 ¼ S 13 |
 T 31 S |
 R 5 W |
 1973

from which
A Fir 8" dia., bears S.20°W., 46½ lks. dist., marked ¼ S13 BT.
A Fir 6" dia., bears N.81½°W., 54½ lks. dist., marked ¼ S13 BT.

Fd. OK by Kris DeGroot, 3/2005 - M 146-19