

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 100474

PRIMARY CORNER DESCRIPTION E. Sec. Cor. for 12 & 13 only, T31-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Butler and Hyde, under Contract #39 dated Jan. 4, 1854 (DCSO records Vol. 18 Page(s) 7778)

A Laurel 4" dia., for cor. of secs. 7, 18, 12 and 13, from which

- A Fir 10" dia., bears N.15°W., 26 lks.
- A Laurel 5" dia., bears S.50°E., 60 lks.
- A Laurel 5" dia., bears N.45°E., 48 lks.

GLO survey by Wm. M. Bushey, under Contract #620 dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7866-67)

Intersect the W bdy. of the tp. and set temp. post. I find the Laurel tree cor. killed by fire and greatly decayed, with marks nearly obliterated, from which

- A Fir 10" dia., bears N.15°W., 26 lks. dist., marked T31S R5W S12 BT. This tree is dead.

The other witness trees are destroyed by fire.

I remove this decayed cor. and set a stone, 18x8x6 ins., 12" in the ground for cor. to secs. 12 and 13, marked with 2 notches on N and 4 notches S edges and raised mound of stone, 3 ft. base, 2½ ft. high, 3 ft. S of cor.

No live trees in limits in T31S R5W; pits impracticable.

BLM resurvey by Berry and Akin, under Group #800, surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15648-49)

Point for the cor. of secs. 12 and 13 only; determined by the method of irregular boundaries, there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½" dia., 20" in the ground, in a mound of stone, 3 ft. base. to top, with brass cap marked:

T 31 S | T 31 S
S 12 | R 4 W
S 13 |
R 5 W | S 18
1973

from which

- A Fir 10" dia., bears S.79°W., 39 lks. dist., marked T31S R5W S13 BT.
- A Fir 12" dia., bears N.53½°W., 66 lks. dist., marked T31S R5W S12 BT.

Fd. OK by Kris DeGroot, 3/2005 - M 146-19