

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 100532

PRIMARY CORNER DESCRIPTION E. 1/4 Corner Sec. 12, only, T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and Geo. Hyde, under Contract #39 dated Jan. 4, 1854 (DCSO records Vol. 18 Page(s) 7777)

Set ¼ sec. post, from which
A Live Oak, 10" dia., bears S.68°E., 6 lks.
A Laurel 10" dia., bears N.22°W., 21 lks.

GLO survey by Wm. M. Bushey, under Contract #620 dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7872-73)

Set temp. post. The ¼ sec. post is gone. I find 1 bearing tree.
At cor. point
Set a stone, 15x12x10 ins. 10" in the ground, for ¼ sec. cor. marked ¼ on W face; from which
A Live Oak 10" dia., (12" now) bears S.68°E., 6 lks. dist., marked ¼ S BT.
The Laurel witness tree in sec. 12 is burnt.
I mark:
A Laurel 8" dia., which bears S.17°W., 26 lks. dist., ¼ S BT.

BLM resurvey by Berry and Akin, under Group #800, Surveyed, Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15650)

Point for the ¼ sec. cor. of sec. 12 only, determined by the method of irregular boundaries, there is no remaining evidence of the original corner.
Set an iron post, 28" long 2½" dia., 24" in the ground, with brass cap marked:
¼ S 12
T 31 S
R 5 W
1973

from which
A Fir 7" dia., bears S.34½°W., 65 lks. dist., marked ¼ S12 BT.
A Fir 6" dia., bears N.88°W., 61 lks. dist., mkd. ¼ S12 BT.

Found OK by B. Shaner, Oct. 2000 - M132-51