

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7855)

-----  
Set a stone 12x8x7 ins., 8" in the ground for 1/4 sec. cor. marked 1/4 on N. face; from which

A Fir 11" dia., bears S.45 1/4°W., 12 lks. dist. mkd. 1/4 S BT.

A Fir 10" dia., bears N.24°E., 33 lks. dist. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: McAllister - Dec. 1949 - C.S. File 40/232

-----  
Determined from O.B.Ts:

13" Fir bearing S.45°W., 8.0 ft. scribe legible.

16" Fir bearing N.23°E., 21.0 ft. remarked "S30 1/4 S".

At corner point, SET 3/4" x 40" Iron pipe, 24" in ground.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - April 1966 - C.S. File 54/20-40

-----  
Found - No trace of iron pipe, 3/4" as recorded.

Orig. 13" Fir now 15", dead snag, S.45°W., 8.0 ft., faint scribing visible.

Orig. 16" Fir now 20", N.23°E., 21.0 ft., shows good scar, "1/4S" bark scribed above old face.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

1/4 S 30  
S 31

1966

New BT - 24" D.Fir S.33°E., 38.0 ft. scribed 1/4 S31 CS BT.

Fd. and used in BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under Group #1217, surveyed Sept. 1984/April 1986 - (DCSO records Vol. 47 Page(s) 18154)