

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7858)

Set a stone 18x6x6 ins., 12" in the ground, for 1/4 sec. cor. marked 1/4 on N. face; from which

A Laurel 16" dia., bears S.39 1/4°E., 41 lks. dist. mkd. 1/4 S BT.

A Fir 18" dia., bears N.53°E., 24 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Wayne L. Rogers, Rick A. McMullen, Lance J. Bishop, Cadastral Surveyors, under Group #1217, surveyed Sept. 1984/April 1986 - (DCSO records Vol. 47 Page(s) 18158-59)

The 1/4 sec. cor., determined from the remains of the original bearing trees:

A root hole, bears N.53°E., 24 lks. dist., with down Fir alongside, 20" dia., with scribe marks 1/4 S visible on decayed blaze.

A Madrone root hole surrounded with Madrone shoots, bears S.39 1/4°E., 41 lks., no marks visible.

At the corner point

Set a stainless steel post, 28" long, 2 1/2" dia., 15" in the ground, to solid rock, in a collar of stone, 3 ft. base, to top, with brass cap mkd:

T 31 S R 4 W

1/4 S 19

S 30

1985

from which new bearing trees:

A Fir 5" dia., bears N.12 3/4°E., 31 lks. dist. mkd. X BT.

A Fir 8" dia., bears S.15 3/4°E., 27 lks. dist. mkd. 1/4 S30 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.