

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7866)

Set a Cedar post, 4 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 S on N. face; from which
A Fir 15" dia., bears N.71 1/4°E., 28 lks. mkd. 1/4 S BT.
A Cedar 10" dia., bears S.12 1/2°W., 53 1/2 lks. mkd. 1/4 S BT.

Survey by Robert M. Thompson - For: Sunny Valley Lumber Co. - July 12, 1959 - M 15-24

Old corner not found.
I set 6" x 8" x 12" quartz stone, from which
18" D.Fir S.74°W., 18.1 ft. alum. tag.
12" D.Fir N.45 1/2°E., 21.6 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - March 1966 - C.S. File 54/20-23

Found - Quart rock set at 1/4 corner.
18" D.Fir now 21", S.74°W., 18.1 ft., scribe visible "BT". (this brg. should be S.64°W.)
12" D.Fir now 14", N.45 1/2°E., 21.6 ft., scribe visible "BT".

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 4 W
1/4 S 7
S 18
1966

Set alongside quartz stone. All BTs in good condition. This corner lies about 50.0 ft. North of ravine.

Bruce Shaner - For: Seneca Jones Timber Co. - March 2002 - M139-61 & C.S. File 65/42-40D

Found - 2" Brass cap on a 1" Iron pipe (properly mkd).
30" D.Fir, face overgrown, bears S.64°W., (rec. S.74°W.) 18.1 ft.
18" D.Fir, now high stump, face overgrown, w/USBLM tin cap, bears N.40°E., (Rec. N.45 1/2°E.) 21.6 ft.
Quartz stone alongside B.C.
6 ft. steel fence post bears South 0.5 ft.
New - 8" W.Fir, scribed "1/4 S7 BT" bears N.21°W., 13.3 ft.
Note - Corners located on E-W cutting line of BLM sale unit (Unit in sec. 7)

Fd. Ok by K. DeGroot, 3/2005 - M 146-19
FD. Ok by T Hostetter, 4/2006 - M154-42