

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Metal fence posts bear approx. 5 ft. West & 2 ft.
South of corner.

Note: Lone Rock Timber ran a random traverse along the section lines from the east $\frac{1}{4}$ to the southeast section corner to the south $\frac{1}{4}$ corner to the southwest section corner of section 6, to mark property lines for timber management purposes. We also ran a GPS survey for survey control at points on our conventional traverse to check our closure. We marked property lines with flagging, blazing, painting, and aluminum boundary tags. Found 1956 Douglas County Cap approx. 60 ft. east of O'shea creek. 2013 BLM pre-commerical thinning to the northeast of section corner.