

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; and 3 & 4, T32-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 18 Page(s) 7783)

Set post, cor. to secs. 3, 4, 33 and 34, from which
A Fir 24" dia., bears N.80°E., 32 lks. dist.
A Fir 5" dia., bears S.48°E., 7 lks. dist.
A Fir 4" dia., bears S.54°W., 22 lks. dist.
A Fir 4" dia., bears N.22°W., 40 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8507)

The Sec. cor., bearing trees on the E. standing; all other accessories to this corner destroyed; from the bearing trees, I reestablish this corner as follows:
Set a Cedar post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 3, 4, 33 and 34, marked T31S S34 on NE.; R4W S3 on SE.; T32S S4 on SW.; and S33 on NW.; faces, with 3 notches on E. and W. edges; from which
A Fir 24" dia., bears N.80°E., 32 lks. dist., marked T31S R4W S34 BT.
A Fir 6" dia., bears S.48°E., 7 lks. dist., marked T32S R4W S3 BT.
An Ash 6" dia., bears S.77°W., 47 lks. dist., marked T32S R4W S4 BT.
A Fir 6" dia., bears N.45°W., 42 lks. dist., marked T31S R4W S33 BT.

Survey by John Markham - For: Stomar Lumber Co. - April 1951 - C.S. File 40/232

At corner point, Set 1" x 24" Iron pipe.
All of the following are O.B.T.s, which I remarked:
A Fir 20" dia., bears N.44°W., 27.0 ft. dist.
An Ash 9" dia., bears S.80°W., 29.3 ft. dist.
A Fir 10" dia., bears S.48°E., 4.6 ft. dist.
A Fir 40" dia., bears East, 21.5 ft. dist., This OBT was already bark scribed S34 R4W 31S BT. The notes call for this tree to bear N.80°E., the distance was correct.

GLO resurvey by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12777)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. cor. for 33 & 34; and 3 & 4, T32-4

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

The Sec. cor., determined at record bearing and distance from the remaining original bearing trees mkd. by Byars in 1871:
 A Fir 40" dia., bears N.80°E., 32 lks. dist., marked T31S R4W S34 BT.

A Fir 14" dia., bears S.48°E., 7 lks. dist., marked S3 on open blaze.

and bearing trees marked by Nicklin in 1897:

An Ash 10" dia., bears S.77°W., 47 lks. dist., marked S4 on open blaze.

A Fir 20" dia., bears N.45°W., 42 lks. dist., marked with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked (Cont. Next Page)

T31S	R4W
S 33	S 34
S 4	S 3
T32S	
1959	

Survey by Geo. J Wenderoth - Dec. 5, 1962 - C.S. File 52/29-2

Found - 1" Iron pipe with brass cap.
 20" Fir S.46°30'E., good, 4.6 ft.
 14" Ash S.81°20'W., good, 29.3 ft.
 24" Fir N.39°45'W., 27.0 ft. Blown down, no tree available.
 Found stump of Orig., now 40" Fir, N.89°15'E., 21.5 ft.
 New BT - 12" Cedar N.48°50'E., 15.9 ft.

BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15466-67)

The Sec. cor., monumented with an iron post, 2½" dia., loosely set, protruding 12" above ground with 1959 brass cap. from which the remains of the original bearing trees:

A sawed Fir stump 40" dia., bears East, 32 lks. dist., with scribe marks BT visible on bark. (Rec. N.80°E.)

A Fir 16" dia., bears S.48°E., 7 lks. dist., mkd. with healed blaze.

and bearing trees mkd. by Nicklin:

A double Ash 11" dia., bears S.79 3/4°W., 44 lks. dist., with scribe marks S and other illegible marks visible on partially healed blaze. (Rec. S.77°W., 47 lks.)

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; and 3 & 4, T32-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A root hole bears N.45°W., 42 lks. dist., with a down Fir alongside 26" dia., with healed blaze. and a bearing tree mkd. by Wenderoth in 1962:

A Cedar 12" dia., bears N.46°E., 22 lks. dist., with scribe marks S34 CS BT visible on partially healed double blaze.

No suitable tree available in NW quadrant.

From this point, a local corner established and recorded by Markham in 1951, bears S.75°W., 0.01 chs. dist., monumented with an iron pipe, 1" dia., firmly set, protruding 8" above ground.

Fd. BLM BC & BTs by Troy Rambo, July 2002 M140-74