

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7834)

A Fir 4" dia., which I mark ¼ S on W. face, for ¼ sec. cor., from which
 A Fir 5" dia., bears N.43°E., 18¾ lks. dist., mkd. ¼ S BT
 A Cedar 16" dia., bears S.32¼°W., 45 lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - March 9, 1960 - C.S. File 42/391-51

Determined by O.B.T.s
 6" Fir snag N.43°E., 11.9 ft., found scribe
 26" Cedar snag bears S.32°W., 29.7 ft., found scribe.
At corner point, found 6" Fir snag mkd. on West face and SET 3/4" x 30" Iron pipe, from which
 4" Fir S.18°E., 21.3 ft. mkd. ¼ S3 BT.
 4" Alder S.40°E., 21.5 ft. mkd. ¼ S3 R4W BT.
 3" Fir S.54°E., 24.0 ft. mkd. ¼ S3 BT.
 3" Alder S.83°W., 3.5 ft. mkd. ¼ S4 BT.
Creek bears South 190.0 ft. dist.

Jerry Estabrook - For: Roseburg Resources - 5/2003 - C.S. File 65/45-32K & M142-36

Found - 3/4" iron pipe 0.7 ft. above grade.
Orig. BTs:
 A Fir snag 6" bears N.43°E., 11.9 ft. not found.
 A Cedar snag 26" bears S.32°W. 29.7 ft. fd. down
A fir 19" with healed face & tag bears S.58°E., (S.54°E.) 24.0 ft.
Alder 13" bears S.83°W., 3.9 (3.5) ft.
Fir 12" with healed face & tag bears S.18°E. 21.3 ft
Unrecorded BTs:
 An Alder 9" with visible scribe, brass face washer "LS2354", tag & nail at side center bears N.12°W., 22.2 ft.
 A D.Fir 10" with visible face scribe bears N.48°E., 33.6 ft.
New - BTs were red band & face painted. Tags were added where needed.
Note - Corner falls on top of a small SE sloped ridge. Land to the West was recently clear cut. Land to the east is still timbered.