

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7787)

Set ¼ sec. post, from which
A Fir 6" dia., bears N.20°W., 9 lks. dist.
A Fir 8" dia., bears S.20°E., 10 lks. dist.

Recorded by F.C. Frear, County Surveyor - Jan. 28, 1921 - Field Book 109 Page 3

Set galvanized iron pipe 1¼" dia. for ¼ post, from which
A Fir 60" dia., bears N.9¼°E., 55 lks., gone.
A Fir 36" dia., bears N.37¼°W., 93 lks.
Renewed in the presence of H. Meranda, Levi Spaulding, Paddy McGinnis and Jim McGinnis.

Douglas County Surveyors Office - George J. Wenderoth - 1956 C.S. File 47/138 (C.S. File 40/29 & M4-75 - 1947)

Found - 1½" Iron pipe.
Also found old witness tree, from which
16" Yew fence corner post, S.85°37'E., 37.2 ft.
12" Fir N.28°W., 64.3 ft.

Douglas Co. Surveyors Office - James Byron - For: Douglas County, Cow Creek Road #36 - Dec. 6, 1956 - Road File Drawer 48/Rd. 36

This corner renewed by Wenderoth, 1956. Corner on fill slope of new county road construction.
Set brass cap at corner using Wenderoth's bearings and distances.
16" Yewwood corner gate post scribed ¼ S CS BT, S.87°37'E., 37.2 ft.
12" R.Fir N.28°W., 64.3 ft. scribed ¼ S27 CS BT.
Marked brass cap 27 ¼ Corner T31S R4W County Surveyors Office, 1966 34.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb. 1966 - C.S. File 54/20-19

Found - Brass cap at ¼ cor. set by County in 1956.
16" yewwood post, S.87°37'E., 37.2 ft., scribe visible.
12" R.Fir now 18", N.28°W., 46.3 ft., shows good scar.
New BT - 8" Fir N.28°E., 88.6 ft., scribed.

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and used in BLM Resurvey by Lynn M. Roseberry and Larry D. Evans, Cadastral Surveyors, under Group #778, surveyed July/Sept. 1972- (DCSO records Vol. 38 Page(s) 15475-76)

3/20/2007 placed * after number because corner is under water in Galesville Dam