

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7824)

Set a stone 16x8x4 ins., 12" in the ground, for ¼ sec. cor. marked ¼ on N. face; from which

A Laurel 10" dia., bears N.52°E., 28 lks. dist. mkd. ¼ S BT.

A Fir 10" dia., bears S.69½°W., 16½ lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - May 13, 1959 - C.S. File 42/391-27

Determined by O.B.Ts:

16" Fir S.69°W., 11.6 ft., found scribe.

At corner point, found stone and SET 1¼" x 36" truck axle, from which

7" Laurel bears N.56°E., 17.5 ft. mkd. ¼ S2 R4W BT.

5" Laurel bears N.28°W., 8.3 ft. mkd. ¼ S2 T31S BT.

14" Live Oak bears N.67°W., 25.0 ft. mkd. ¼ S2 BT.

11" Laurel bears S.33°W., 24.1 ft. mkd. ¼ S11 R4W BT.

Carl Sweeden - For: Rome Creek Timber - Aug. 2013 - M165-61

Condition Report only

Found - Truck axle with flange end up & iron rod along side square head bolt along side (orig.)

17" D.Fir BT stump, S.69°W., 11.6', scar vis., tag, no bark

1959 REPORT:

7" Laurel BT, N.56°E., 17.5', rotted mound

9" Laurel BT, N.28°W., 8.3', scribe vis., broken top, tree is alive

7" D.Fir BT, S.54½°E. 29.5', scribe vis. dbl blazed, tag.

15" Live Oak BT, N.67°W., 26.0', scribe vis. in lower and upper blaze, tag

18" Laurel BT stump, S.33°W., 24.1', 0.9' tall.